

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

ALL OIL, GAS, AND
DEEPWATER
ARTESIAN, AND
OTHER COPIES RETURNED
(Other instructions on re-
verse side)

NM Roswell District
Notified Form No.
11560-3160-4

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER P-A

2. NAME OF OPERATOR: Julian Ard

3. ADDRESS OF OPERATOR: 302 Main Street, Suite 302 Fort Worth, Texas 76102

4. LOCATION OF WELL: 1980' F.N.L. 1980 F.E.L. Sec. 25 T19S R30E

14. PERMIT NO. _____

15. ELEVATIONS (Show whether DF, RT, GR, etc.): 3306 GR 3327 RKB

3a. Area Code & Phone No.: (817) 335-3715

5. LEASE DESIGNATION AND SERIAL NO.: NM 06767

6. IF INDIAN, ALLOTTEE OR TRIBE NAME: _____

7. UNIT AGREEMENT NAME: _____

8. FARM OR LEASE NAME: Hackberry

9. WELL NO.: 1

10. FIELD AND POOL, OR WILDCAT: Wildcat

11. SEC., T., R., M., OR R1K. AND SURVEY OR ARPA: 25 T19S R30E

12. COUNTY OR PARISH: Eddy

13. STATE: NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	FILL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACURE TREAT	MULTIPLE COMPLETION	FRACURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT*
REPAIR WELL	CHANGE PLANE	(Other)	
(Other)			X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Displace hole with mud.
2. Set C.I. B.P. @ 9200' ± 35' cement on top.
3. Cut 5½ csg. @ 7180' ± 150' cement plug @ stub. Must tag this plug. Will set plug with 2 7/8" bg.
4. Set 150' Cement plug @ 5600' ± 2 7/8" bg.
5. Set 100' Cement plug @ 8 5/8" csg. shoe. Tag plug.
6. Set 100' Cement plug @ 3100' ± S.A.
7. Set 100' Cement plug @ D.V. Tool 2184'.
8. Set 100' Cement plug @ 820' ± 13 3/8" csg. shoe.
9. Set 50' Cement plug @ surface, with permanent marker. Dry Hole. Witnessed by J Sanchez w/ BLM
10. Move equipment off, level off location, close all pits.

18. I hereby certify that the foregoing is true and correct

SIGNED: [Signature] TITLE: President DATE: 12-11-89

APPROVED BY: [Signature] TITLE: _____ DATE: 12-15-89

CONDITIONS OF APPROVAL, IF ANY:
Approved by _____
Licensed by _____
Signed by _____

*See Instructions on Reverse Side