

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-4026

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Howell "29" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Cemetery (Morrow)

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 29, T-20-S, R-25-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to recomplete or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

JAN 27 1976

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

DAVID FASKEN ✓

3. ADDRESS OF OPERATOR

O. C. C.
ARTESIA, OFFICE
608 First National Bank Building, Midland, Texas 797014. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit M, 1300' FSL & 1300' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3592' K.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other) & open additional Morrow section for production

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rig up pulling unit.
2. Kill well with 4% KCl water & install B.O.P.'s.
3. Pull 2-3/8" tubing and packer.
4. Perforate Morrow "B" Zone with 4 jets per foot from 9250'-9270' with 3-3/8" hollow casing carrier.
5. Run packer and tubing and swab-in well.
6. Test through separator into N.G.P.L.'s line.
7. Stimulate perforations as required.
8. Flow well to clean up.
9. Put well on stream and test.

This work proposed to start about January 26, 1976.

RECEIVED

JAN 26 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

Robert H. Angevine

SIGNED

TITLE

Agent

DATE

1-23-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side