State of New Mexico Form C-103 Submit 3 Copies , Minerals and Natural Resources Department to Appropriate District Office Revised 1-1-89 OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 SECEIVED Santa Fe, New Mexico 87504-2088 30-015-21572 DISTRICT II 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 FEE L STATE DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410 6. State Oil & Gas Lease No. SEP 20 '90 V - 2531SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT*RESIA, OFFICE 7. Lease Name or Unit Agreement Name (FORM C-101) FOR SUCH PROPOSALS.) RE-ENTRY 1. Type of Well: State "D" - SWD OTHER DEEPEN METT [WELL 2. Name of Operator 8. Well No. YATES PETROLEUM CORPORATION L 9. Pool name or Wildcat 3. Address of Operator 105 South 4th St., Artesia, NM 88210 Wildcat Devonian 4. Well Location Line and 1980 Feet From The West __ Feet From The __South 660 Line Unit Letter ... Eddy 24E 20S hip 20S Range 24E 10. Elevation (Show whether DF, RKB, RT, GR, etc.) **NMPM** County Township Section 3761' GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 11. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PLUG AND ABANDON REMEDIAL WORK ALTERING CASING PERFORM REMEDIAL WORK PLUG AND ABANDONMENT **CHANGE PLANS** COMMENCE DRILLING OPNS. **TEMPORARILY ABANDON** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** OTHER: Drill out DV tool, perforate, treat X OTHER:_ 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. Rig up. Pick up 2-7/8" workstring. Drill out DV tools. Run bit and scraper to TD. Perforated 9723-11052' with total 532 - .41" holes as follows: 10963-969, 10980-982, 10986-988, 10744-754 (2 SPF-32 holes), 10639-643 (2 SPF-10 holes), 10528-532, 10520-524, 10512-516 (2 SPF-

11004-014, 11025-036, 11048-052 (1 SPF-41 holes); 9723-26, 9732-37, 9739-41, 9748-57, 9764-67 (1 SPF-27 holes), 10885-887, 10900-916 (2 SPF-40 holes), 10860-864 (2 SPF-10 holes), 10794-798, 30 holes), 10432-457, 10416-422, 10404-410, (2 SPF-80 holes), 10394-400, 10340-350, 10314-320 (2 SPF-50 holes), 10280-292, 10233-241, 10207-222 (2 SPF-76 holes), 10184-188, 10176-180, 10152-160, 10126-140, 10114-122, 10106-108, 10100-102, 10093-094 (2 SPF-98 holes), 9938-42, 9882-88, 9847-50, 9830-32 (2 SPF-38 holes). Acidized perfs 9723-9767' w/2500g. 15% NEFE acid and 30 ball sealers. Swabbed - no gas that would burn. POH w/RBP and packer. RIH w/tubing and knock out disk. Set over Bliss Sand @ 10940'. Dropped bar on disc. Slight blow for 1 minute. Made 3 swab runs-no flow. *Acidized w/3000 g. 15% NEFE acid and 50 ball sealers.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. TIME Production Supervisor 9-18-90 bo dlive SIGNATURE TELEPHONE NO. 505/748-1471 Juanita Goodlett TYPE OR PRINT NAME

*10963-11052'

(This space for State Use)

APPROVED BY -

SEP 2 8 1990

CONDITIONS OF AFTROVAL, IP ANY: