

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Mack Energy Corporation

3. Address and Telephone No.

P.O. Box 1359 Artesia, NM 88211-1359 (505) 748-1288

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec.14 T-18-S R-31-E 660' FSL & 1980' FWL

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

NM 28096

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No. #1

Swearinger Deep 14 Fed

9. API Well No.

20-05-25889

10. Field and Pool, or Exploratory Area

Tomah Bone Springs

11. County or Parish, State

Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other

☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Set 5 1/2 CIBP @ 7700' cap W/ 10 sx cement
- 2) Load hole with mud
- 3) Spot 25 sx cement plug @ 6825'
- 4) Spot 25 sx cement plug @ 3450'
- 5) SPot 25 sx cement plug @ 2397' across 8-5/8 shoe
- 6) Cut 5 1/2 casing @ 1516' pull out of hole
- 7) Spot 35 sx cement plug @ 5 1/2 stub 1568' W.O.C. tag cement top @ 1520' no cement above 5 1/2 stub, spot 25 sx cement @ 1520' W.O.C. tag cement top @ 1520' no cement above 5 1/2 stub spot 30 sx cement @ 1520' W.O.C. tag cement top @ 1385'
- 8) SPot 35 sx cement plug @ 423' across 13-3/8 shoe
- 9) Spot 50' surface plug & set PA marker
- 10) Job completed 5-16-97

Approved as to plugging of the well bore
Liability under bond is retained until
surface restoration is completed.

Post
P&H

RECEIVED
JUN 11 A 10:43
BUREAU OF LAND MGMT.
WELL OFFICE

14. I hereby certify that the foregoing is true and correct

Signed Alexis C. Swoboda

Title Supervisor

Date 5-16-97

(This space for Federal or State office use)

Approved by (ORIG. SGD.) ALEXIS C. SWOBODA

Title PETROLEUM ENGINEER

Date JUN 10 1997

Conditions of approval, if any: