

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-28415

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Hinkle ALD

8. Well No.
3-H

9. Pool name or Wildcat
Dagger Draw Upper Penn, North

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3471' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location Proposed BHL: 660' FNL & 760' FEL of Section 28-T19S-R25E (Unit A, NENE)
Unit Letter H : 1980 Feet From The North Line and 660 Feet From The East Line

Section 28 Township 19S Range 25E NMPM Eddy County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Drill out CIBP <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-12-2000 - TIH with whipstock fishing tool and engage workstring. TOOH and laid down work-string and tools. Shut well in.

10-13-2000 - TIH with 6-1/8" bit with bumper sub, drill collars and tagged CIBP at 7642'. Worked CIBP to 7648'. Pulled above window. Shut well in.

10-14-2000 - Tagged CIBP at 7648'. Washed off top of plug - no fill. Resumed jarring on CIBP. Pushed plug 4'. Pulling unit is having brake problems. Plus is moving up and down in a 4' area but will not release. Shut well in.

10-15-2000 - Rigged up power swivel. Rotated on CIBP at 7648'. Jarred on plug. Brakes on pulling unit slipped and dropped all the weight on bottom. Picked up and lost 6000#. TOOH - found 62 bent joints of tubing. Laid down bent tubing. Did not have any drill collars. Shut well in.

10-16-2000 - Picked up overshot with extension, bumper sub, oil jars, drill collars and new tubing. Strapped in hole and set down on fish. Worked overshot over fish and picked up. Gained 6000#. Weight would fall to string weight. Could not keep extra weight.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CONTINUED ON NEXT PAGE:

SIGNATURE Rusty Klein TITLE Operations Technician DATE Oct. 30, 2000

TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

NOV 16 2000