Submit 3 Copies to Appropriate Ener District Office	State of New Mexico Ainerals and Natural Resources Department	- Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	CONSERVATION DIVISION P.O. Box 2088	WELL API NO.
DISTRICT.II Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210		30-015-28543 5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL		Marshall APH
2. Name of Operator		8. Well No.
YATES PETROLEUM CORPORATION 3. Address of Operator 105 South 4th St., Artesia,	AUG 2 4 1995	9. Pool name or Wildcat Dagger Draw Upper Penn, North
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North Line and</u> <u>1980</u> Feet From The <u>West</u> Line		
Section 9 Township 19S Range 25E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3527' GR 3527' GR 10. 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
	UG AND ABANDON ABANDON REMEDIAL WORK ANGE PLANS COMMENCE DRILLING CASING TEST AND CE OTHER:_Product.	
 12. Describe Proposed or Completed Operations (Clearly state all periment data), and give periment dates, including estimated date of starting any proposed work) SEE RULE 1103. TD 8250'. Reached TD at 12:15 AM 8-20-95, Ran 203 joints of 7" 26# & 23# casing as follows: 17 joints of 7" 26# N-80 sandblasted (688.68'); 3 joints of 7" 26# J-55 sandblasted (121.92'); 1 7" 26# N-80 sandblasted marker joint (20.50'); 61 joints of 7" 26# J-55 sandblasted (2511.79'); 90 joints of 7" 23# J-55 varnished (3653.69'); 26 joints of 7" 26# J-55 varnished (2511.79'); 90 joints of 7" 26# N-80 varnished (184.73') (Total 8255.41') of casing set at 8250'. Float shoe set at 8250'. Float collar set at 8212'. DV tool set at 6020'. Marker joint set at 7439'. Circulating sub set at 8171'. Cemented in two stages as follows: Stage 1: 500 sacks Super "C", 4/10% CF-2, 4/10% CF-14A, 3.42#/ sack salt and 8#/sack hiseal (yield 1.68, weight 13.0). PD 5:00 PM 8-21-95. Bumped plug to 2000 psi for 2 minutes. Circulated 117 sacks. Circulated through DV tool for 3-1/2 hours. Stage 2: 850 sacks Pacesetter Lite C, 5#/sack gilsonite, 5#/sack salt and 1/4#/sack celloseal (yield 2.01, weight 12.5). Tailed in with 100 sacks Class H Neat (yield 1.18, weight 15.6). PD 10:15 PM 8-21-95. Bumped plug to 3000 psi for 2 minutes. Circulated 118 sacks. Released rig at 2:30 AM 8-22-95. Waiting on completion unit. 		
TYPE OR PRINT NAME RUSTY Klein		тецерноме но. 505/748-1471
(This space for State Use) ORIGINAL SIGN DISTRICT II SU	PERVISOR	DATE AUG 2 9 1995