

NO. OF COPIES RECEIVED	1
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED
NEW MEXICO OIL CONSERVATION COMMISSION

DEC 20 1972

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

O. C. C.
ARTESIA, OFFICE

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Dry</u>		7. Unit Agreement Name <u>Catclaw Draw</u>
2. Name of Operator <u>Hanagan Petroleum Corporation</u>		8. Farm or Lease Name <u>Catclaw Draw Unit</u>
3. Address of Operator <u>P. O. Box 1737, Roswell, New Mexico 88201</u>		9. Well No. <u>8</u>
4. Location of Well UNIT LETTER <u>G</u> <u>1960</u> FEET FROM THE <u>North</u> LINE AND <u>1650</u> FEET FROM THE <u>East</u> LINE, SECTION <u>22</u> TOWNSHIP <u>21S</u> RANGE <u>25E</u> NMPM.		10. Field and Pool, or Wildcat <u>Undesignated</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3475 KB</u>		12. County <u>Eddy</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug & abandon as discussed with Mr. Gressett as follows:

(TD 10781' sh.) Set 35 sx plugs (100') in 7-7/8" open hole @ 10650-10750; 10300-10400; 8650-8750; 7450-7550; 4000-4100; 1860-1960 (in & out 8-5/8" csg. set @ 1910), 10 sx plug @ surface w/appropriate dry hole marker, heavy drilling mud between all plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Hugh C. Hanagan</u>	TITLE <u>Vice President</u>	DATE <u>12/19/72</u>
APPROVED BY <u>W. A. Gressett</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>DEC 20 1972</u>
CONDITIONS OF APPROVAL, IF ANY:		