PLICATE* (Other instructions on re-DEPARTMENT OF THE INTERIOR verse side)

GEOLOGICAL SURVEY

CopytoSF

5. LEASE DESIGNATION AND SERIAL NO.

APR 3 0 1975

O. C. C. ARTESIA, OFFICE

0455265

	l										
SUNDRY NOTICES AND REPORTS ON WELLS	'	6.	IF	, I;	NDIA	Ν,	ALLOT	CEE	OR ?	TRIRE	NAME

(Do not use this form for propos	ICES AND REPORTS ON WELLS sals to drill or to deepen or plug back to a different reservoir. ATION FOR PERMIT" for such proposals.)	U. IF INDIAN, ALLOTY	THE OR THIRE NAME		
OIL GAS WELL OTHER	Dry Hole	7. UNIT AGREEMENT	NAME		
2. NAME OF OPERATOR David Fasken		8. FARM OR LEASE N			
3. ADDRESS OF OPERATOR 608 First National Ba	ank Building, Midland, Texas 79701	9. WELL NO.			
4. LOCATION OF WELL (Report location of See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT				
1980' FNL & 6	660' FEL	11. SEC., T., R., M., OF SURVEY OR ARE	BLK. AND		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE			
	3412' K.B.	Eddy	New Mexico		
16. Check Ar	propriate Box To Indicate Nature of Natice Report of	r Other Data			

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:						
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS	x	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of mu Completion or Recompletion)	ALTERING WELL ALTERING CASING ABANDONMENT* Iltiple completion on Well Report and Log form.)					
7 - NUSCOTOR DOCUMENT OF 60	AFDI DIED	ODERATIONS (Clearly state	- 11		••					

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- 1. T.D. 11,259'.
- 2. Will run drill pipe to 11,050' and circulate 9.1#/gal. mud to condition hole for plugging. RECEIVED
- 3. The following plugs will be set:

SACKS	TYPE	TOP	BOTTOM
30 35 55 35 50 35 45	Class "C" "" "" "" "" "" ""	10,950' 10,670' 9,200' 7,700' 5,550' 4,100' 2,900'	11,050' 10,770' 9,350' 7,800' 5,700' 4,200' 3,050'

4. Cut off well head, set 10 sx. surface plug, weld cap on casing.

5. Install dry hole marker.

6. Level pits and clean up location.

ARTESIA, NEW MEXICO 18. I hereby certify that the foregoing is true and correct Robert H. Angevine Agent DATE _4-23-75 TITLE geve-(This space for Federal or State office

*See Instructions on Reverse Side

APPROVAL, IF ANY: ACTING DISTRICT ENGINEER