$\alpha \lambda S_{\alpha}$	
Submit 3 Copies To Appropriate District State of New Mex	ico Form C-103
Office Energy Minerals and Natura	Resources Revised March 25, 1999
District I 1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30015-20935
District II OII CONSERVATION 1	DIVISION 5. Indicate Type of Lease
811 South First, Artesia, NM 86210 District III 2040 South Pache	
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 875	6. State Oil & Gas Lease No.
2040 South Pacheco, Santa Fe, NM 87505	Z V V Unit Agreement
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUDIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	SUCH
PROPOSALS.)	Cedar State
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator	8. Well No.
Concho Resources Inc.	9. Pool name or Wildcat
3. Address of Operator 110 W. Louisiana Ste 410; Midland, Tx 79701	Avalon Bone Spring East
4. Well Location	
South line and 1980 feet from the West line	
Section 11 Township 21s	Range 27E NMPM Eddy County
10. Elevation (Show whether DR, RKB, RI, GR, etc.)	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF.
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
BUILL OR ALTER CASING MULTIPLE	CASING TEST AND CEMENT JOB
COMPLETION	
OTHER: MIT/Casing Integrity Test	OTHER:
OTHER: MIT/Casing Integrity Test 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
of starting any proposed work). SEE ROLL 1103. For interspect to 1	
Concho Resources Inc. respectfully requests approval to perform a M	IT test, to allow for permanently state at states,
Concho Resources Inc. respectfully requests approval to perform a MIT test, to allow for permanently shut in status, according to the following procedure for the Cedar State No. 1 well. 1. Notify OCD to witness test. 2. POOH w/ tbg. 3. RIH w/ CIBP & set @ 6550'. 4. Load hole w/ 2% KCL & test to 500 psi.	
1. Notify OCD to witness test.	
2. POOH w/ tbg.	
 RIH w/ CIBP & set @ 6550'. Load hole w/ 2% KCL & test to 500 psi. 	a profived
4. Load hole w 270	13 OCO ARTESTA
	1300
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
TITLE	7 1 77 0 12 00
SIGNATURE	Telephone No. 915-683-7443
Type or print name Terri Stathem	Telephone (10. 715 005 7715
(This space for State use)	-//
APPPROVED DI VI WESS WE SOLL	Field 300 F
Conditions of approval, if any:	