

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires July 31, 1996

5. Lease Serial No.

**NM92756**

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

**OXY Fig Newton #1  
Federal**

9. API Well No.

**30-015-31098**

10. Field and Pool, or Exploratory Area

**WC MORROW**

11. County or Parish, State

**EDDY NM**

*SUBMIT IN TRIPLICATE - Other instructions on reverse side*

1. Type of Well

Oil Well  Gas Well  Other

2. Name of Operator

**OXY USA WTP Limited Partnership**

3a. Address

**P.O. Box 50250, Midland, TX 79710-0250**

3b. Phone No. (include area code)

**915-685-5717**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**1980 FNL 660 FWL SWNW(E) Sec 4 T20S R27E**

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

Notice of Intent

Subsequent Report

Final Abandonment Notice

Acidize

Alter Casing

Casing Repair

Change Plans

Convert to Injection

Deepen

Fracture Treat

New Construction

Plug and Abandon

Plug Back

Production (Start/Resume)

Reclamation

Recomplete

Temporarily Abandon

Water Disposal

Water Shut-Off

Well Integrity

Other \_\_\_\_\_

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

SEE OTHER SIDE

Accepted for record

only **FEB 1 2002**



14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

**David Stewart**

Title

**Sr. Regulatory Analyst**

Date

**1/20/02**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

OXY FIG NEWTON FEDERAL NO. 1 (Plug & Abandon)

09/19/2001

Daily Cost: \$7131 CUM Cost: \$7131 AFE Cost: \$0  
road unit & crew to loc., move in matting boards, pipe racks & cat walk, spot  
& rig up, sitp 0#, sicp 250#, open csg. to pit, csg. would not bleed down, ru  
reverse pump, load tbg. w/30 bw, load csg. w/60 bw, nd tree, nu 5 k hyd. bop, casing  
started flowing back, release pkr. & pump 65 bw, sisd!

09/20/2001

Daily Cost: \$2754 CUM Cost: \$9885 AFE Cost: \$0  
sicp 350#, bleed well down to pit, load csg. w/50 bw, pooh w/192 jts. 2  
3/8" tbg., si, load csg., attend oxy safety meeting in hobbs, sd!

09/21/2001

Daily Cost: \$4362 CUM Cost: \$14247 AFE Cost: \$0  
sip 100#, bleed down, finish pooh w/ tbg. & pkr., ru rotary wl, rih & set cibp  
@8478', pooh, rih w/dump bailer & dump 5 sacks of cmt. on top of cibp, pooh, rd  
wl, rih w/tbg. to 8443', spot mud from 8443' to 7970', pooh, ru wl, rih & tag  
8443', pooh, rih w/cibp, set @ 7970', pooh, rih w/ dump bailer, dump 5 sacks  
of cmt. on top of cibp, pooh, rd wl, sisd!

09/22/2001

Daily Cost: \$4362 CUM Cost: \$18609 AFE Cost: \$0  
ru wl, rih & tag @ 7927', pooh, wl operator ran into pack off & parted wl  
@ rope socket & dropped sinker bar & collar locator to bottom, rd wl, restring  
blocks to 6 line, rih w/tbg. to 7926', displace hole w/10# mud, pooh w/tbg., sisd!

09/25/2001

Daily Cost: \$8927 CUM Cost: \$27536 AFE Cost: \$0  
ru rotary wl, rih w/ jet shot, cut csg. @ 7077', pooh, rd wl, nd bop, spear  
csg., pull 180,000# & could not move csg., ru csg. jacks, pu to 189,000#  
& csg. was moving thru slips, try to work slips out of wellhead w/no success, nd  
csg. jacks, release spear, nu bop, sisd!

09/26/2001

Daily Cost: \$7128 CUM Cost: \$34664 AFE Cost: \$0  
sip 0#, nd bop, load csg. w/20 bbls. mud, ru welder & tack slips to csg., ru  
csg. jacks, spear csg. & pull slips, rd csg. jacks, nu bop, ru csg. crew, pooh  
& lay down 157 jts. 5.5" csg. & 2 cut jts., rd csg. crew, sisd!

09/27/2001

Daily Cost: \$18153 CUM Cost: \$71744 AFE Cost: \$0  
change bop rams, move out 5.5" csg. & cat walk, rih w/2 3/8" bullplugged  
perforated sub & 225 jts. 2 3/8" tbg. to 7136', ru bj services, load csg.  
w/ 72 bm, mix & pump 65 sx class "C" neat cmt., rd bj, pooh w/42 jts. tbg. to  
5710', sisd!

09/28/2001

Daily Cost: \$4526 CUM Cost: \$76270 AFE Cost: \$0  
rih & tag top of cmt. plug @ 6994', pu to 5053', stand by for bj to repair  
cmt. pump, ru bj, try to pump thru tbg. & could'nt, rd bj, pooh, lay down 11  
jts. cmt. plugged tbg., rih w/ 2 3/8" bull plugged perf. sub & 159 jts.  
2 3/8" tbg. to 5053', ru bj, load hole w/mud, mix & pump 65 sx class C neat  
cement to spot plug from 5053' - 4848', pooh to 3084', ru bj, mix & pump 65  
sx class C w/ 2% calcium chloroxide to spot plug from 3084' - 2887', pooh  
w/40 jts. to 1880', reverse out tbg., sisd!

09/29/2001

Daily Cost: \$15431 CUM Cost: \$91701 AFE Cost: \$0  
rih & tag @ 2998' (30 low), mix & pump 12 sx class c w/2% calcium chloride  
to bring toc to 2865', pu to 454', mix & pump 55 sx class c neat cmt. to  
spot plug from 454' to 287', pooh, nd bop, rih w/ 2 jts., pump cmt. to  
surface, pooh, rig unit down, sd! (will dig out cellar & cut off wellhead on  
monday)