

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN
(Other instructions
verse side)

CATS
OR 70-

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals.)

1. LEASE DESCRIPTION AND SERIAL NO.
NM0532516

2. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. WELL AGREEMENT NAME
Sandy Unit

8. FARM OR LEASE NAME
Sandy Unit

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
Nash (Morrow)

11. SEC. T. R. N. OR BLK. AND
SUBST OR AREA
Sec 24, T-23-S, R-30-E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mex.

3. OIL WELL GAS WELL OTHER

4. NAME OF OPERATOR
Phillips Petroleum Company

5. ADDRESS OF OPERATOR
4001 Penbrook, Odessa, TX 79762

6. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
Unit E, 660' FW and 1980' FN

14. PERMIT NO.
30-015-21126

15. ELEVATIONS (Show whether SP, WT, OR, etc.)
3289 RKB, 3288 DF, 3267 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDISE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDISING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(Other) Plug and Abandon wellbore

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NOTE: Circulate hole volume with mud-laden fluid of at least 9.5 ppg from PBTD (14180') to surface prior to setting the first plug. MI RU DDU. Bleed well down. ND wellhead. NU 6" 5000" BOP's. Do not exceed 140,000# lift removing tree. Pick up straight on 2-7/8" EUE 8RD 6.5# N-80 tubing and attempt to pull packer @ 14,202'. If unable to release, RU wireline truck and cut 2-7/8" tubing off above Model G Locator. COOH and lay down 57 jts. 2-7/8 8RD 6.5# N-80 tubing and 457 jts 2-7/8" 6.5# N-80 C5 Hydril tubing. Perform gauge ring run to 14,180' for 5-1/2" 20# casing. COOH. GIH with 5-1/2" CIBP on wireline and set at 80'. GIH with 2-3/8 EUE 8RD 4.7# N-80 workstring to 14,180'. Circulate hole with 9.5 ppg. Spot Plug No. 1 (45 sx. cement) 13980-14180'. Pull 2-3/8 tubing to 11,710'. Spot Plug No. 2 (35 sx. cement) 11,610-11710'. This covers the liner top @ 11,660'. Pull 2-3/8 tubing to 11,140'. Spot Plug No. 3 (45 sx. cement) 11,040-11140'. This will cover the Wolfcamp @ 11,140'. Pull 2-3/8 tubing to 10,685'. Spot Plug No. 4 (45 sx. cement) 10,585-10685'. This will cover the 3rd Bone Springs @ 10,685'. Pull 3/8 tubing to 7,750'. Spot Plug No. 5 (50 sx. cement) 7,600-7,750'. This will cover the Bone Springs 7,738 and DV Tool at 7,700'. Pull 2-3/8 tubing to 3,950'. Spot Plug No. 6 (50 sx. cement) 3,768-3,950'. This will cover 8-5/8 shoe @ 3,900' and Bone Springs @ 3,868'. Pull 2-3/8 tubing to 1,080'. Spot Plug No. 7 (25 sx. cement) 980-1,080'. This will cover base of salt section @ 980'. Pull 2-3/8 tubing to 515'. Spot Plug No. 8 (125 sx. cement) 3'-515'. COOH. Fill 7-5/8 as needed. This will cover top salt section, 16" casing shoe & surface Plug. Cut off csg 3' below GL.

18. I hereby certify that the foregoing is true and correct (OVER)

SIGNED [Signature] TITLE Supv., Reg./Proation DATE 2/20/92

U. M. Sanders (915) 168-1488

APPROVED BY [Signature] TITLE _____ DATE 4-14-92

CONDITIONS OF APPROVAL, IF ANY:

NOTIFY BLM AT (505) 887-6544 PRIOR TO ANY WORK.

*See Instructions on Reverse Side