

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPL  
(Other instructions  
verse side)

TE\*  
re

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-15295

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR

C & K Petroleum, Inc. ✓

3. ADDRESS OF OPERATOR

P. O. Drawer 3546, Midland, TX 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1650' FSL & 1748' FEL, Sec. 8, T-24-S, R-26-E, Eddy Co., NM

7. UNIT AGREEMENT NAME

JUN 22 1981

8. FARM OR LEASE NAME

"CK" Federal

9. WELL NO.

2-Z

10. FIELD AND POOL, OR WILDCAT

Undesignated-Delaware

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 8, T-24-S, R-26-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3481.9 GR

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to plug and abandon because the well is not economical to produce.

Casing Record:


2000' of 8-5/8", 24#, 11" Hole  
2991' of 5-1/2" 7-7/8" Hole

Perforations:

2619 - 2635'; 2700 - 2785'; 2803 - 2870'.  
PBSD: 2961'

Plugging Procedure:

Set CIBP at 2560', top with 35 linear feet of cement *with dump bailer or 25' x minimum if thru tubing.*  
Free point casing, shoot off and pull.  
Spot 50 sk plug 50' in 5-1/2" casing.  
*25' sk* plug at surface.  
Hole to be filled with mud laden fluid.



18. I hereby certify that the foregoing is true and correct

SIGNED

*L. Lucille Zeehl*

TITLE

Administrative Supervisor

DATE

June 18, 1981

(This space for Federal or State office use)

APPROVED

APPROVED BY

(Orig. Sgd.) PETER W. CHESTER

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 23 1981

FOR

JAMES A. GILLHAM \*  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side