

Copy to F

GEOLOGICAL SURVEY

NM-0476505

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. OIL WELL GAS WELL OTHER RECEIVED

7. UNIT AGREEMENT NAME

2. NAME OF OPERATOR Robert N. Enfield ✓

8. FARM OR LEASE NAME Bolton-Federal

3. ADDRESS OF OPERATOR P.O. Box 2431, Santa Fe, N.M. 87501

9. WELL NO. 1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface

10. FIELD AND POOL, OR WILDCAT Wildcat

1980' FNL & 660' FWL, Sec. 19

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

T-25-S, R=27-E, Sec. 19

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3245 Gr

12. COUNTY OR PARISH Eddy

13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input checked="" type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cut and pull 4 1/2" casing.
Set 100' plug at top of 4 1/2" casing.
100' plug @ top of Salt.
20 sack plug at surface.

RECEIVED
JAN 29 1974
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

Vertical text stamp: RECEIVED FEB 14 1974 U.S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct
SIGNED Robert N. Enfield TITLE Operator DATE 1-23-74

(This space for Federal or State office use)
APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

APPROVED
FEB 14 1974
K. L. BEEKMAN
ACTING DISTRICT ENGINEER

TITLE _____ DATE _____

*See Instructions on Reverse Side