

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0133
Expires September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

3. Lease Designation and Serial No.
LG-5340

6. If Indian, Allotment or Tribal Name

SUBMIT IN TRIPLICATE

1. Type of Well
 Oil Well Gas Well Other Gas Storage Well

2. Name of Operator
El Paso Natural Gas Co.

3. Address and Telephone No.
P.O. Box 1492, El Paso, Texas 79978 (915) 541-2600

4. Location of Well (Permit, Sec., T., R., M., or Survey Description)
2310' FNL & 660' FEL
SEC. 32, T-25-S, R-24-E

7. If Utes or CA, Agreement Designation

Washington Ranch

8. Well Name and No.
Storage OB #5

9. API Well No. Project #10

10. Field and Pool, or Exploratory Area
Wsh. Rnch Mor.

11. County or Parish, State
Eddy Co., N.M.

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION |
|--|--|
| <input checked="" type="checkbox"/> Notice of Intent | <input checked="" type="checkbox"/> Abandonment |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Recompletion |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Plugging Back |
| | <input type="checkbox"/> Casing Repair |
| | <input type="checkbox"/> Altering Casing |
| | <input type="checkbox"/> Other |
| | <input type="checkbox"/> Change of Plans |
| | <input type="checkbox"/> New Construction |
| | <input type="checkbox"/> Non-Routine Fracturing |
| | <input type="checkbox"/> Water Shut-Off |
| | <input type="checkbox"/> Conversion to Injection |

Plug & Abandon

(Note: Report results of multiple completions on Well Completions or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data, including estimated date of starting any proposed work. If well is ultimately drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Page 1 of 3

- 1) Notify BLM/OCD of intentions to P&A OB #5
- 2) Inspect Location, WH Connection, Deadmen, etc.
- 3) MI & RU PU & Surface Equipment.
- 4) RU Kill Truck & Mud Truck (Premixed) & circ. Mud to kill Well and load Hole w/ minimum 9 #/gal. Mud (25 #/bbl. salt gel mixed in 9 #/gal. brine).
- 5) ND WH & NU BOP.
- 6) POOH w/ 234 Jts. 2 7/8" Tbg. (approx. 7303') & clean, inspect and tally for use as Workstring.
- 8) RU WL & Run GR to 7150' (top perf. @ 7191').
- 9) RIH w/ 5 1/2" CIBP on WL & set @ 7150'. POOH.
- 10) RIH w/ Perf. Gun & Perf. 4 holes (.5" dia.-180 phase-2 SPF) @ 3980'. POOH w/ Gun & RD WL.

(Continued on next page)

14. I hereby certify that the foregoing is true and correct
Signed Dave Brewster Title Reservoir Engineer Date 10/22/92

(This space for Federal or State official use)

Approved by _____ Title _____ Date _____
Consent of approval, if any.