

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

| | | | |
|--|--|--|--|
| OPERATOR | | <input checked="" type="checkbox"/> Initial Report | <input checked="" type="checkbox"/> Final Report |
| Name of Company: Chevron USA Inc. | Contact: James A. Trujillo | | |
| Address: 15 Smith Rd., Midland, TX, 79705 | Telephone No.: work: 575-704-3146 cell: 575-650-3602 | | |
| Facility Name: Central Vacuum Unit Battery | Facility Type: Battery | | |
| Surface Owner N/A | Mineral Owner N/A | API No. | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| E | 31 | 17S | 35E | | | | | Lea |

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release: Vent | Volume of Release: 6,375.15 MCF | Volume Recovered: 0 MCF |
| Source of Release: Flare | Date and Hour of Occurrence: 06/22/15 11:07 AM | Date and Hour of Discovery: 06/22/15 11:07 AM |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Kellie Jones, OCD | |
| By Whom? Nick Hampton | Date and Hour: 06/23/2015 09:06 AM | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* N/A | <div>RECEIVED By OCD District 1 at 1:20 pm, Jun 23, 2015</div> | |



Describe Cause of Problem and Remedial Action Taken.*

The Buckeye CO2 Plant lost its compressors which resulted in a venting (flare did not ignite) event at CVU Battery. For remedial action taken, Vacuum Production was shut in.

Describe Area Affected and Cleanup Action Taken.*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|----------------------------|---|--|
| Signature:  | | OIL CONSERVATION DIVISION | |
| Printed Name: James A. Trujillo | | Approved by Environmental Specialist:  | |
| Title: HES Field Specialist | Approval Date: 06/23/2015 | Expiration Date: // | |
| E-mail Address: jtqo@chevron.com | Conditions of Approval: // | Attached <input type="checkbox"/> 4323 1RP-3687 | |
| Date: 06/23/15 | Phone: 575-650-3602 | | |

* Attach Additional Sheets If Necessary

nKJ1517451534