

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	BC Operating, Inc.	Contact	Pam Stevens
Address	P.O. Box 50820, Midland, Texas 79710	Telephone No.	432-684-9696
Facility Name	Government 'E' SWD #1	Facility Type	SWD
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-025-23708

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	25	19S	34E	600	South	1880	West	Lea

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced Salt Water	Volume of Release	500 bbls	Volume Recovered	480bbls
Source of Release	Injection pump water suction tanks	Date and Hour of Occurrence		Date and Hour of Discovery	7:00 a.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	on 06/16/15 Kelly		
By Whom?	Pam Stevens	Date and Hour	3:56 p.m. on 06/16/15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

**RECEIVED**  
By OCD District 1 at 10:17 am, Jul 01, 2015

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Water transfer process pump out-ran injection pump causing water to overflow the injection pump water tanks. Reset pump controller to prevent recurrence.

Describe Area Affected and Cleanup Action Taken.\*  
Inside firewall. Vacuum truck picked up 480 bbls.  
Dirt was dug up and another 18 of 20 bbls from sumps was hauled off.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Pam Stevens</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Pam Stevens		Approved by Environmental Specialist: <i>Ke...</i>	
Title: Regulatory Analyst	Approval Date: 07/01/2015	Expiration Date: <b>To remain open until final closure.</b>	
E-mail Address: pstevens@bcoperating.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7/1/15	Phone: 432-684-9696	<b>1. RP-3681 will remain open until the site is decommissioned and delineated.</b>	

- 2. At abandonment, delineation will be conducted to ensure proper understanding of historic releases, at which point a new depth of excavation will be determined.**
- 3. Ensure BLM concurrence/approval.**

\* Attach Additional Sheets If Necessary