

APPROVED

By OCD District 1 at 3:33 pm, Jul 08, 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	575-628-4121
Facility Name	CE Lamunyon #74	Facility Type	Well location
Surface Owner	Jimmy Weir	Mineral Owner	
		API No.	30-025-35060

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	27	23S	37E	1310	North	1515	West	Lea County, NM

Latitude N 32.27893°Longitude W 103.15399°**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 8 bbls produced water	Volume Recovered	0 bbls
Source of Release	A piece of rubber was stuck in the back pressure valve which caused the stuffing box packing on the wellhead to blow out	Date and Hour of Occurrence	05/11/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD		
By Whom?	Kathy Purvis, BBC International	Date and Hour	05/12/2014 @ 3:05pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*	<div>RECEIVED By OCD District 1 at 3:32 pm, Jul 08, 2015</div>				

Describe Cause of Problem and Remedial Action Taken.*

A piece of rubber got stuck in the back pressure valve which caused the stuffing box packing to blow out on the well head and spill 2 bbls of oil and 8 bbls of produced water onto the ground. The piece of rubber was removed, the stuffing box packing was replaced, and no fluids were recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 10' x 90' on location. Remediation was completed in accordance with the remediation plan approved by Tomas Oberding of NMOCD via email on 10/20/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: **Chris Jones**
Digitally signed by Chris Jones
DN: cn=Chris Jones, o, ou,
email=ckjones88@yahoo.com,
c=US
Date: 2015.05.15 10:43:14 -05'00'

Printed Name: Christopher Jones

Approved by Environmental Specialist:

Title: HES Specialist

Approval Date: **07/08/2015**

Expiration Date: //

E-mail Address: Christopher.Jones@oxy.com

Conditions of Approval:

Attached ☐
IRP-3340

Date: Phone: 575-628-4121 //

* Attach Additional Sheets If Necessary