

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company BRIDGER LLC	Contact RODNEY GALINDO
Address 2009 CHENAULT DR #100, CARROLLTON, TX	Telephone No. 469-704-9138
Facility Name State HF Tank Battery	Facility Type Tank Battery/Load Line

Surface Owner OXY	Mineral Owner OXY	API No.
-------------------	-------------------	---------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	9	19S	38E	188	North	317	West	Lea

Latitude 32.6815 Longitude -103.1524

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 18 bbls	Volume Recovered 0 bbls
Source of Release Load Line between tank and sales connection	Date and Hour of Occurrence 7/7/15 11:40 am	Date and Hour of Discovery 7/8/15 9:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED
By OCD District 1 at 7:38 am, Jul 20, 2015

Describe Cause of Problem and Remedial Action Taken.*

Sales valve on the tank was not properly closed by the tanker truck driver, upon discovery of the release, the valve was immediately closed.

Describe Area Affected and Cleanup Action Taken.*

Crude oil flowed away from the tank and load line, affected the pad and surrounding area. A one-call has been made, all affected soil over NMOCD remedial limits will be excavated, disposed and the area will be backfilled. Bridger will submit documentation of remedial actions and confirmation sampling in a Corrective Action Report once all activities are complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
		Approved by Environmental Specialist: 	
Printed Name: Rodney Galindo		Approval Date: 7/20/2015	Expiration Date: 10/20/2015
Title: West Texas Field Safety Rep		Conditions of Approval:	
E-mail Address: rgalindo@bridgergroup.com		Discrete site samples required. Delineate and remediate per NMOCD guidelines. Geotagged photographs of remediate required.	
Date: 7/10/2015	Phone: 469-704-9138	Attached <input type="checkbox"/> IRP-3738	

* Attach Additional Sheets If Necessary

nJXK1520127211

pJXK1520127464