

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company OCCIDENTAL PERMIAN LTD.	Contact TONY AGUILAR
Address 1017 W. Stanolind Road, Hobbs	Telephone No. (575)397-8251
Facility Name NORTH HOBBS UNIT RCF/WIB	Facility Type OIL AND GAS PRODUCTION FACILITY
Surface Owner Occidental Permian LTD.	Mineral Owner HOBBS (G-SA)
Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	25	18-S	37-E					Lea

Latitude 32°43'14.96" Longitude 103°11'59.65"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 1821 MCF	Volume Recovered 0
Source of Release RCF FLARE SSM EVENTS	Date and Hour of Occurrence 7/15/2015 5:21:00 AM	Date and Hour of Discovery 7/15/2015 5:21:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? MAXEY BROWN	
By Whom? TONY AGUILAR	Date and Hour 7-14-15	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA	<div style="border: 2px solid blue; padding: 5px; display: inline-block;"> <p>RECEIVED By OCD District 1 at 7:46 am, Jul 28, 2015</p> </div>	

Describe Cause of Problem and Remedial Action Taken.*
Cause:
FLARED INTERMITTENTLY AT THE NORTH NOBBS UNIT REINJECTION COMPRESSOR FACILITY (RCF). A-TRAIN DOWN DUE TO COMPLETE ANNUAL PM WHILE NHU SATELLITE 19C DEPRESSURIZED FOR MAINTENANCE, AND DOWN AGAIN DUE TO LUBE NO FLOW SHUTDOWN. C-TRAIN DOWN TO DOWN LOAD NEW PROGRAM. EOR
Remedial Action Taken:
A-TRAIN RESTARTED AFTER TIE-INS AND MAINTENANCE WERE MADE AT NHU SATELLITE 19C. C-TRAIN WAS RESTARTED AFTER NEW PROGRAM WAS INSTALLED.

Describe Area Affected and Cleanup Action Taken.*
ALL GAS BURNED AT FLARE.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: TONY AGUILAR	Approved by District Supervisor: 	
Title: NES Specialist	Approval Date: 7/28/2015	Expiration Date: ///
E-mail Address: RAYMOND_AGUILAR@OXY.COM	Conditions of Approval: ///	
Date: 7-23-15 Phone: (575)397-8251	Attached <input type="checkbox"/> IRP 3765	

* Attach Additional Sheets If Necessary

pJXK1520927848

nJXK1520927733