<u>District</u>	
1625 N. French Dr., Hobbs, NM 88240	
District II	
811 S. First St., Artesia, NM 88210	
District III	
1000 Rio Bruzos Road, Aztec, NM 87410	
District IV	
1220 S. St. Francis Dr., Santa Fe, NM 875	05

State of New Mexico	4171
Energy Minerals and Natural RECEIVED	Form C-141 Revised August 8, 2011
Oil Conservation Divi By Jamie at 3:54 p	om, Sep 22, 2015
Santa Fc, NM 87505	
Release Notification and Corrective Action	

THE THE TOTAL OF THE				
	OPERATOR	🛛 Initial Report	Final Report	
of Company Oxy Permian Ltd.	Contact Dusty Wilson	······································		
6 Darts Drive Midland TV 20205				

		Z mula report _ rital report
Name of Company Oxy Permian Ltd.	Contact Dusty Wilson	
Address 6 Desta Drive, Midland, TX 79705	Telephone No. (432) 685-5771	
Facility Name Thomas A #003	Facility Type Well	
Surface Owner Pruett	Mineral Owner	API No. 30-025-26139

LOCATION OF RELEASE								
Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feat from the	East/West Line	County
LJ	19	245	<u>37E</u>					Lea County, NM

Latitude N 32.20099°

Longitude <u>W 103,19897°</u>

NATURE OF RELEASE					
Type of Release Oll and produced water	Volume of Release S bbls oil,	Volume Recovered 5 bbls			
	7 bbls produced water				
Source of Release Stress/fatigue of 3" poly flow line	Date and Hour of Occurrence	Date and Hour of Discovery			
	09/06/2015				
Was Immediate Notice Cliven?	If YES, To Whom?				
Yes 🛛 No 🗋 Not Required	Kellie Jones, Jamie Keyes, & Tomas Oberding-NMOCD				
By Whom? Kathy Purvis, BBC International	Date and Hour 09/08/2015				
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.				
🗌 Yes 🖾 No					
If a Watercourse was Impacted, Describe Fully.*					
an man an mamanan an sera seestan mananda mananga sa sesta sa sesta sa sesta sa sesta sa sesta sa sesta sa sest					
Describe Cause of Problem and Remedial Action Taken.*					
Stress/fatigue of a flow line caused 5 bbls of oil and 7 bbls of produced w	ater to leak onto the ground. A vacuur	n truck recovered 5 bbts of fluids and the			
line was repaired/replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 38' x 20' off location just north of the entrance road. Remediation will be completed in accordance with a remediation plan approved by NMOCD.					
han abbreact of manyory.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and					
regulations all operations are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger					
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability					
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health					
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other					
federal, state, or local laws apoor regulations.	see astronove no operator of response	work for exulusinen with any other			
4/4//	OIL CONSERV	ATION DIVISION			
	ULL VUNDER V.	MILLIN LAVIORUN			

Signature:	OIL CONSERVAT	ION DIVISION	
Printed Nape: Dusy Wilson	Approved by Environmental Specialist:		
Title: Environmental Advisor	Approval Date: 09/22/2015 Expir	ation Date: 11/22/2015	
E-mail Address: Dusty Wilson@oxy.com	Conditions of Approval;		
Date: 9/21/15 Phone: (432) 685-5771	Discrete site samples required. Delineate remediate per NMOCD guidelines.	and Attached 1 1RP 3872	
Attach Additional Sheets If Neccessary	Geotagged photos of remediation requir	ed.	

nJXK1526557088

pJXK1526557221