

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 9:36 am, Nov 04, 2015

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Cimarex Energy	Contact	Christine Alderman
Address	600 N Marienfeld Ste 600 Midland TX	Telephone No.	432-853-7059
Facility Name	Southern California 29 Fed 18	Facility Type	production

Surface Owner	BLM	Mineral Owner		API No.	30-025-39889
---------------	-----	---------------	--	---------	--------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	29	19S	32E	1140	N	33	E	Lea

Latitude 32.63552 Longitude -103.78079

#### NATURE OF RELEASE

Type of Release crude oil	Volume of Release 17 bbls	Volume Recovered 14 bbls
Source of Release heater treater	Date and Hour of Occurrence 10/6/2015	Date and Hour of Discovery 10/6/2015
Was Immediate Notice Given? <div><input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required</div>	If YES, To Whom? Jamie Keyes/Kellie Jones/Shelly Tucker	
By Whom? Christine Alderman	Date and Hour 10/8/2015 8:30am	
Was a Watercourse Reached? <div><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No</div>	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

**APPROVED**

By JKeyes at 9:36 am, Nov 04, 2015

Describe Cause of Problem and Remedial Action Taken.\*

The dump valve on the heater treater became plugged with paraffin and did not work properly

Describe Area Affected and Cleanup Action Taken.\*

14 bbls of oil were contained and recovered within a LINED containment. 3 bbls were oversprayed onto the location pad. Location was backdragged.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Christine Alderman</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Christine Alderman		Approved by Environmental Specialist: <i>Jamie Keyes</i>	
Title: ESH Supervisor		Approval Date: 11/04/2015	Expiration Date: ///
E-mail Address: calderman@cimarex.com		Conditions of Approval:	
Date: 10/9/2015 Phone: 432-853-7059		Ensure BLM concurrence/approval	Attached <input type="checkbox"/> IRP 3954

\* Attach Additional Sheets If Necessary

nJXK1530834348

pJXK1530834488