

APPROVED**By Kellie Jones at 7:33 am, Dec 09, 2015**

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: Legacy Reserves Operating, LP	Contact: Freddie Gibbs
Address: 303 W. Wall St. Ste 1300, Midland, TX 79701	Telephone No. 432-664-1692
Facility Name: Rock Queen Unit #86	Facility Type: Well

Surface Owner: State	Mineral Owner: State	API No. 30-005-00931
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 36	Township 13S	Range 31E	Feet from the 1980	North/South Line North	Feet from the .660	East/West Line West	County Chaves
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 33.1485596 Longitude -103.7815247**NATURE OF RELEASE**

Type of Release: Mixed Fluids	Volume of Release: 20bbls	Volume Recovered: 5bbls
Source of Release: Flowline	Date and Hour of Occurrence: 8/28/2015	Date and Hour of Discovery: 8/28/2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

REVIEWED**By Kellie Jones at 7:33 am, Dec 09, 2015**

Describe Cause of Problem and Remedial Action Taken.*

A flowline leaked causing a release of approximately 20bbls of mixed fluids. A vacuum truck was utilized to recover approximately 5bbls of fluid.


Describe Area Affected and Cleanup Action Taken.*

The impacted area was in the pasture southeast of the location. Talon/LPE was contacted to conduct a site assessment and soil sampling within the impacted area. Upon receipt of analytical results from the soil sampling events a remediation work plan was drafted and subsequently approved by NMOCD. The remediation was conducted to the scope laid out in the approved work plan. The area was backfilled and contoured to match the surrounding terrain.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISIONSignature: 

Printed Name: Freddie Gibbs

Approved by Environmental Specialist: 

Title: Production Superintendent

Approval Date: 12/09/2015

Expiration Date: //

E-mail Address: fgibbs@legacyp.com

Conditions of Approval:

Date: 11/20/15

Phone: 432-644-1692

Attached ☐
IRP-3900

* Attach Additional Sheets If Necessary