

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Jeff Heath, Devon Completions Asst. Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575- 513-2274
Facility Name: Black Mamba 15 State Com 8H	Facility Type : Well location associated with spill #1 (north)

Surface Owner at spill: State	Mineral Owner at spill: Federal	API No. 30-025-42630
--------------------------------------	--	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	25	22S	33E	521	North	1285	East	Lea

Latitude: **32.368610** Longitude: **-103.521860**

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 35 bbls	Volume Recovered: 0 bbls
Source of Release: Water transfer line	Date and Hour of Occurrence 12/4/2015; 5:15 PM	Date and Hour of Discovery 12/4/2015; 5:15 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Kellie Jones	
By Whom? Jeff Heath, Devon Asst. Completions Foreman	Date and Hour: OCD: 12/5/2015; 10:28 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* NA		

RECEIVED

By Kellie Jones at 8:51 am, Dec 11, 2015


Describe Cause of Problem and Remedial Action Taken.*

Because a pinhole leak was discovered in a produced water transfer line from the North Gaucho pond to the Black Mamba 15 State Com 8H while prefilling frac tanks, the pumps were shut down and line clamps were installed to isolate a small section of the line to be repaired. When the line was cut to make repairs, the head pressure on the line was high enough that the line clamps were not able to hold all the pressure back, resulting in a release of produced water. Once the pressure was low enough, the line clamps held and repairs were able to be made.

Describe Area Affected and Cleanup Action Taken.*

The spill area affected is approximately 8' x 100' x 2" deep following an existing 2-track in the field approximately 4.37 miles northeast of the Black Mamba 15 State Com #8H. Approximately 35 barrels of produced water was spilled and none was recovered, all water soaked into the sand. An environmental company has been called to test and create a remediation plan for submittal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: 	
Title: Field Admin Support	Approval Date: 12/11/2015	Expiration Date: 02/11/2016
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: Site samples required. Delineate and remediate as per MNOCD guides. Geotag photographs of remediation recommended.	Attached <input type="checkbox"/> IRP-4010
Date: 12/9/2015 Phone: 575-746-5544		

* Attach Additional Sheets If Necessary

nKJ1534531959
pKJ1534535662



12/4/15 spill Blk Mamba



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
 Prepared by: D Menoud
 Map is current as of: 09-Dec-2015

