

**APPROVED****By Kellie Jones at 2:37 pm, Jan 19, 2016**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chevron	Contact: Nick Hampton
Address: 15 Smith Rd., Midland, TX, 79705	Telephone No. wk: 575-704-3143 cell: 985-502-2342
Facility Name: WDDU #42; IRP# 3535	Facility Type: Injection Well

Surface Owner: State	Mineral Owner: State	API No. 30-025-12321
----------------------	----------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter A	Section 32	Township 24S	Range 38E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------

Latitude: N 32° 10' 44.36" Longitude: W 103° 4' 32.23"

#### NATURE OF RELEASE

Type of Release: <u>produced water</u>	Volume of Release: <u>9 bbls</u>	Volume Recovered: <u>5 bbls</u>
Source of Release: <u>Crack in nipple on B1 hanger</u>	Date and Hour of Occurrence: <u>2/11/15 @ 11:30 am</u>	Date and Hour of Discovery: <u>2/11/15 @ 11:30 am</u>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: <u>Not Applicable</u>	

If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Describe Cause of Problem and Remedial Action Taken.\*  
Spill was due to crack in nipple on B1 Hanger.

Describe Area Affected and Cleanup Action Taken.\*

Spill area was around the well head and then 600 FT down the road. Vacuum Truck was called out to vacuum up standing fluids recovered 5 bbls of fluids and cleaned up the area. The release area has been excavated and samples collected. Based on laboratory analytical data and NMOCD approval the excavation has been partially lined with a 20 mil poly-ethylene liner and backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: Nick Hampton

Printed Name: Nick Hampton

Title: HE Specialist

E-mail Address: cikb@chevron.com

Date: 12/9/15

Phone: 985-502-2342

Approved by Environmental Specialist: Kellie Jones

Approval Date: 01/19/2016

Expiration Date: //

Conditions of Approval:

//

Attached ☐  
1RP-3535

\* Attach Additional Sheets If Necessary