

**From:** [Yu, Olivia, EMNRD](mailto:Yu.Olivia.EMNRD)  
**To:** [bcccorp@aol.com](mailto:bcccorp@aol.com)  
**Cc:** [agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us); [tpassmore@mar-win.com](mailto:tpassmore@mar-win.com)  
**Subject:** RE: Marshall & Winston IRP-4680  
**Date:** Friday, October 13, 2017 9:41:00 AM  
**Attachments:** approved\_1RP4680\_Marshall & Winston Klein 16 State 2H Closure Report.pdf

---

Good morning Mr. Porter:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **1RP-4680** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

Like approval from NMLSO is required. Please see the attachment for your records.

Thanks,

Olivia Yu  
Environmental Specialist  
NMOCD, District I  
[Olivia.yu@state.nm.us](mailto:Olivia.yu@state.nm.us)  
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

**From:** bcccorp@aol.com [mailto:bcccorp@aol.com]  
**Sent:** Tuesday, September 26, 2017 8:08 AM  
**To:** Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>  
**Cc:** agroves@slo.state.nm.us; tpassmore@mar-win.com  
**Subject:** Re: Marshall & Winston IRP-4680

Good morning Olivia,

The attached file contains some 'after' pictures and a short summary / closure report for the remedial activities taken for IRP-4680. Please let me know if you need anything else.

Thank you!  
Paul Porter  
BCC, Inc.

Office # 1 800.765.3478  
Cell # 806.790.1698

[www.bcccorp.com](http://www.bcccorp.com)



-----Original Message-----

From: Yu, Olivia, EMNRD, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>

To: bcccorp <[bcccorp@aol.com](mailto:bcccorp@aol.com)>

Cc: agroves <[agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us)>; tpassmore <[tpassmore@mar-win.com](mailto:tpassmore@mar-win.com)>

Sent: Thu, Aug 24, 2017 10:04 am

Subject: RE: Marshall & Winston IRP-4680

Mr. Porter:

NMOCD grants backfill approval. Please submit a short summary to serve as a closure report along with the final C-141.

Like approval from NMSLO is required.

Thanks,  
Olivia

Sent from Samsung Mobile

----- Original message -----

From: [bcccorp@aol.com](mailto:bcccorp@aol.com)

Date: 08/24/2017 07:43 (GMT-07:00)

To: "Yu, Olivia, EMNRD"

Cc: [agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us), [tpassmore@mar-win.com](mailto:tpassmore@mar-win.com)

Subject: Re: Marshall & Winston IRP-4680

Olivia,

The excavated areas are not separated from each other (I probably did not get enough 'after' excavation pictures for you). There is one large open hole out there right now. I used GPS tracking to outline the excavated areas (page 3 of the document attached) and this is actually a slightly larger area than the original spill area (page 2). Please let me know if you need anything else.

Thank you!  
Paul Porter

BCC, Inc.

-----Original Message-----

From: Yu, Olivia, EMNRD, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>  
To: bcccorp <[bcccorp@aol.com](mailto:bcccorp@aol.com)>  
Cc: agroves <[agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us)>; tpassmore <[tpassmore@mar-win.com](mailto:tpassmore@mar-win.com)>  
Sent: Thu, Aug 24, 2017 8:28 am  
Subject: RE: Marshall & Winston IRP-4680

Good morning Mr. Porter:

Thank you for the reminder. Please address these questions regarding 1RP-4680. Based on the photos, it appears that the excavated areas are separated from each other. True? If so, please amend the scaled map with the outlines of each of the separated excavated areas with the locations of the confirmation sample points as currently marked.

Thanks,  
Olivia

**From:** [bcccorp@aol.com](mailto:bcccorp@aol.com) [<mailto:bcccorp@aol.com>]  
**Sent:** Thursday, August 24, 2017 6:55 AM  
**To:** Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>  
**Cc:** [agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us); [tpassmore@mar-win.com](mailto:tpassmore@mar-win.com)  
**Subject:** Fwd: Marshall & Winston IRP-4680

Good morning Olivia,

I am just checking in to see if you have had time to review our request to proceed with backfilling the excavated areas for the Klein 16 State 2H release (IRP-4680)? Please let me know if this is accepted.

Thank you!  
Paul Porter  
BCC, Inc.

-----Original Message-----

From: bcccorp <[bcccorp@aol.com](mailto:bcccorp@aol.com)>  
To: olivia.yu <[olivia.yu@state.nm.us](mailto:olivia.yu@state.nm.us)>  
Cc: agroves <[agroves@slo.state.nm.us](mailto:agroves@slo.state.nm.us)>  
Sent: Mon, Aug 14, 2017 8:06 am  
Subject: Marshall & Winston IRP-4680

Good morning Olivia,

The attached file contains the confirmation sidewall and bottom soil sample analysis, several digital pictures taken during excavation, and the related documents for IRP 4680. With your approval, we would like to proceed with backfilling the areas with clean soil. Please let me know if this is accepted.

Thank you!  
Paul Porter  
BCC, Inc.