Dear Ms. Flores:

Note: PLSS is incorrect on the first page of the closure report.

The closure report for 1RP-2838, 1RP-2876, and 1RP-2880 is DENIED. Please provide documentation that corrective action activities (i.e., delineation, remediation, abatement) were conducted for each of these incidents. NMOCD has documentation for 1RP-2880 of chloride-impacted soil to 55 ft. bgs without resolution.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I <u>Olivia.yu@state.nm.us</u> 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Laura Flores [mailto:lflores@diversifiedfsi.com]
Sent: Wednesday, April 26, 2017 3:41 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Cc: Michael Burton <mburton@diversifiedfsi.com>; Hickert, Aaron <AHickert@linnenergy.com>; TButters@linnenergy.com; Haines, Jeff <JHaines@linnenergy.com>
Subject: Linn - Humphrey Queen Battery (HQU #016) (1R-2880, 1R-2876, 1R-2838) Closure Request

Ms. Yu,

Attached is the Closure Request for the Humphrey Queen Battery (HQU #016) (1R-3880, 1R-2876, 1R-2838) site.

Please let me know if you have any questions or require additional information.

Thank you,

Laura Flores Report Writer Environmental Department Diversified Field Service, Inc. 206 W Snyder | Hobbs, NM 88240 Phone: 575.964.8394 | Fax: 575.964.8396