

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	HAUMEA STATE #002H	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-025-40833

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	36	19S	35E	330'	North	1980'	East	Lea

Latitude 32.6231804 Longitude 103.4085999

NATURE OF RELEASE

Type of Release:	Oil & Produced Water	Volume of Release:	160bbls of Oil & 14bbls of Produced Water	Volume Recovered:	155bbls of Oil & 165bbls of Produced Water mixed with rain water
Source of Release:	Gasket on fire tube	Date and Hour of Occurrence:	09-06-2016 1:30 pm	Date and Hour of Discovery:	09-06-2016 1:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Keyes - NMOCD / Ms. Groves - SLO		
By Whom?	Robert Grubbs Jr.	Date and Hour:	09-06-2016 09:26 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

APPROVED

By Olivia Yu at 3:31 pm, Dec 18, 2017

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a gasket that failed on a fire tube due to corrosion. Move production fluid to a different tank.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho had the free fluids and any contaminated material inside the lined facility removed. The liner has been cleaned and returned back to normal operations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:	
Title:	Senior Environmental Coordinator	Approval Date:	12/18/2017
E-mail Address:	rgrubbs@concho.com	Expiration Date:	xx/xx/xxxx
Date:	October 20, 2016	Phone:	432-683-7443
		Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

1RP-4439