

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Chevron USA, Inc.	Contact: Amy Barnhill
Address: 6301 Deauville Blvd., Midland, TX 79706	Telephone No.: 432-687-7108
Facility Name: R E COLE "A" TB #7	Facility Type: Central Tank Battery

Surface Owner: State	Mineral Owner: State	API No.: 30-025-10316
----------------------	----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	16	22S	37E	554	North	554	East	Lea

Latitude: **32.39261** Longitude: **-103.1456** NAD83

NATURE OF RELEASE

Type of Release: Spill in secondary lined containment	Volume of Release: 6.85 bbls produced water and .51 bbls oil	Volume Recovered: 6.85 bbls produced water and .51 bbls oil
Source of Release: Tank overflow	Date and Hour of Occurrence: 8-24-16 @ 2:00pm	Date and Hour of Discovery: 8-24-16 @ 2:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jamie Keyes	
By Whom? Josepha Deleon	Date and Hour: 8-24-16 @ 2:30pm via voice message	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

APPROVED

By Olivia Yu at 12:30 pm, Aug 09, 2018



Describe Cause of Problem and Remedial Action Taken.*

Tank run over due to RICE operating's disposal line back flowing on our lease. Pump lost power in the storm and the check valves were bad due to corrosion which contributed to this as well. Shut in and called vac truck was called to pick up the spill.

Describe Area Affected and Cleanup Action Taken.* Reference IRP-4433

All in secondary, lined containment. Recovered all the fluid, there is gravel/dirt on top of the plastic liner and was cleaned with microbial product (Gator).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amy Barnhill	Approved by Environmental Specialist: 	
Title: Waste/Water Specialist	Approval Date: 8/9/2018	Expiration Date: xx/xx/xxxx
E-mail Address: ABarnhill@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6-25-18 Phone: 432-687-7108	Like approval from NMSLO.	

* Attach Additional Sheets If Necessary

1RP-4433

Chevron U.S.A. Inc.

R.E. COLE "A"

TANK BATTERY #7

UNIT G, SEC. 16, T22S, R37E

TANKS #10180-10181





