Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

	OPERATOR	Initial Report	Final Report
Name of Company Devon Energy Production Company	Contact Aaron Kidd; Foreman	Technical Services	
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-748-3371		
Facility Name Shinnery 14 Federal 5	Facility Type Salt Water Dispo	sal	

Surface Owner	Federal	Mineral Owner Federal	API No.30-025-30719

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
Н	14	18S	32E					Lea

Latitude_32.748062 N_ Longitude -103.730759 W_ NAD83

Type of Release Produced Water Volume of Release 264 BBLS Volume Recovered 90 BBLS Source of Release Fiberglass Water Tanks Date and Hour of Occurrence 7/26/2018 @ 9:20 AM MST Date and Hour of Discovery 7/26/2018 @ 9:20 AM MST Was Immediate Notice Given? Yes No Not Required BLM Shelly Tacker ENMRD Olivia Yu and Christina Hernandez By Whom? Brett Fulks; EHS Professional Date and Hour of Courrence 7/26/2018 @ 12:24 PM MST Trees (State Course) Was a Watercourse Reached? Yes No NA Was a Watercourse was Impacted, Describe Fully.* N/A RECEIVED By CHernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* RECEIVED By CHernandez at 6:59 am, Aug 14, 2018 A lease operator discovered that lighting struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire promptly. Approximately 264 bbls of produced water, rain water, and extinguishing media used by the fire department. Describe Area Alfected and Cleanup Action Taken.* No Water released to location pad. Dit to outsimment herm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering Muds (W: Spillel - 264 bbls, Rec 90 bbls, Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and underestand that pursuant to NMOCD rules and regu	NATURE OF RELEASE							
Was Immediate Notice Given? Yes No Not Required TYES, To Whom? By Whom? Brett Fulks; EHS Professional Oct and BLM 7/27/2018 @ 12:24 PM MST ENMRD Olivia Yu and Christina Hernandez. By Whom? Brett Fulks; EHS Professional Oct and BLM 7/27/2018 @ 12:24 PM MST Oct and BLM 7/27/2018 @ 12:24 PM MST Was a Watercourse Reached? Yes No N/A N/A By Whom? Brett Fulks; EHS Professional Oct and BLM 7/27/2018 @ 12:24 PM MST Frequencing and the second the second and the second and the second and t	Type of Release Produced Water	Volume of Release 264 BBLS	Volume Rec	covered 90 BBLS				
Was Immediate Notice Given? Yes No Not Required If YES, To Whom? By Whom? Brett Fulks; EHS Professional Date and Hour OCD and BLM 7/27/2018 @ 12:24 PM MST Was a Watercourse Reached? Yes No NA If a Watercourse Reached? Yes No NA Describe Cause of Problem and Remedial Action Taken.* RECEIVED By Chernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* Received water released based on wineless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleamp Action Taken.* No Interest taken and run off location side and onto lease troad; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "final Report" does not relieve the operator of liability should their organia and/or regulations. Signature: Tamala J. Robison Approval Date: 8/14/2018 Expiration Date: Frinted Name: Tamala	Source of Release Fiberglass Water Tanks							
By Whom? Brett Fulks; EHS Professional Date and Hour OCD and BLM 7/27/2018 @ 12:24 PM MST Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A NA By Whom? Brett Fulks; EHS Professional Date and Hour OCD and BLM 7/27/2018 @ 12:24 PM MST If a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A NA Describe Cause of Problem and Remedial Action Taken.* RECEIVED A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the free promptly. Approximately 264 bbls, of produced water relaced based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Ditr containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation at the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operation have failed to adequately invest			7/26/2018 @	9:20 AM MST				
ENMRD Olivia Yu and Christina Hernandez By Whom? Brett Fulks; EHS Professional Date and Hour OCD and BLM 7/27/2018 @ 12:24 PM MST Was a Watercourse Reached? If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* A lease operator discovered that lightings struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire promptly. Approximately 264 bbls of produced water released based on wireless tank readings at the time of the incident. Vacuum tracks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls, Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform does not relieve the operator of itability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulation								
By Whom? Brett Fulks; EHS Professional Date and Hour OCD and BLM 7/27/2018 @ 12:24 PM MST Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. N/A N/A By Whom? Brett Fulks; EHS Professional If YES, Volume Impacting the Watercourse. N/A N/A Describe Cause of Problem and Remedial Action Taken.* RECEIVED By CHernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire promptly. Approximately 264 bbls of produced water relaxed based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dit containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spillel - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Filan Report" does not relieve the operator of liability should their o	Yes No Not Required							
OCD and BLM 7/27/2018 @ 12:24 PM MST Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. NA NA Describe Cause of Problem and Remedial Action Taken.* RECEIVED By Chernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* Receive at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* Receive at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* By Chernandez at 6:59 am, Aug 14, 2018 Describe Area Affected and Cleanup Action Taken.* Receive at the fully.* Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for comp		ENMRD Olivia Yu and Christ	ina Hernandez					
OCD and BLM 7/27/2018 @ 12:24 PM MST Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. NA NA Describe Cause of Problem and Remedial Action Taken.* RECEIVED By Chernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* Receive at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* Receive at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* By Chernandez at 6:59 am, Aug 14, 2018 Describe Area Affected and Cleanup Action Taken.* Receive at the fully.* Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for comp	By Whom? Prott Fulles: EUS Professional	Data and Hour						
Was a Watercourse Reached? Yes X No If Yes, Volume Impacting the Watercourse. N/A If a Watercourse was Impacted, Describe Fully.* N/A NA RECEIVED Describe Cause of Problem and Remedial Action Taken.* Received State Control Conterve Contenter Contentent and Conter Control Control Control Cont	by whom? Dieu Purks, Eris Professional							
□ Yes No N/A If a Watercourse was Impacted, Describe Fully.* RECEIVED N/A RECEIVED Describe Cause of Problem and Remedial Action Taken.* Receive Cause of Problem and Remedial Action Taken.* A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire promptly. Approximately 264 bbls of produced water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of fiesophishilty for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamada J. Robison Approved by Environmental Specialist: Expiration Date: Printed Name: Tamala J. Robison Ap	Was a Watercourse Reached?							
NA By CHernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire propriomately 264 bbls of produced water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releaves which may endanger public health or the environment. In addition, NMOCD acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not re								
NA By CHernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire propriomately 264 bbls of produced water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releaves which may endanger public health or the environment. In addition, NMOCD acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not re								
By CHernandez at 6:59 am, Aug 14, 2018 Describe Cause of Problem and Remedial Action Taken.* A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire promptly. Approximately 264 bbls of produced water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of liability for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison Approved by Environmental Specialist: Printed Name: Tamala J. Robison Approval Da		RECEIVED						
Describe Cause of Problem and Remedial Action Taken.* A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire promptly. Approximately 264 bbls of produced water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface w	NA	By CHernande	ez at 6:59 an	n Aug 14 2018				
A lease operator discovered that lightning struck the fiberglass water tanks at the Shinnery 14 Fed 5 SWD. The fire department was notified and extinguished the fire promptly. Approximately 264 bbls of produced water released based on wireless tank readings at the time of the incident. Vacuum trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approval Date: 8/14/2018 Expiration Date: E-mail Address: Tamala Robison@dvn.com Conditions of Approval: Attached	Describe Cause of Problem and Remedial Action Taken.*		2 at 0.00 an	i, rug 11, 2010				
trucks were able to recover 90 bbls of fluid which was a combination of produced water, rain water, and extinguishing media used by the fire department. Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approval Date: 8/14/2018 Expiration Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached		ks at the Shinnery 14 Fed 5 SWD.	The fire department	t was notified and				
Describe Area Affected and Cleanup Action Taken.* Water released to location pad. Dirt containment bern gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approved by Environmental Specialist: Printed Name: Tamala J. Robison Conditions of Approval Title: Field Admin Support Approval Date: B-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371								
Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approval Date: 8/14/2018 Expiration Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached	trucks were able to recover 90 bbls of fluid which was a combination of p	produced water, rain water, and ex	tinguishing media	used by the fire department.				
Water released to location pad. Dirt containment berm gave way causing the PW to leave the containment area and run off location side and onto lease road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approval Date: 8/14/2018 Expiration Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached								
road; immediately began recovering fluids. (PW: Spilled - 264 bbls., Rec 90 bbls., Lost - 174 bbls.) I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approval Date: 8/14/2018 Expiration Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached bate: 7/30/2018 Phone: 575-748-3371 Attached		the DW to leave the containment	ana and mun off la	action side and onto loose				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: <i>Tamala J. Robison</i> OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approved by Environmental Specialist: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371			area and run off fo	cation side and onto lease				
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached Attached	Toad, minediatery began recovering nulus. (1 w. Spined - 204 bois., Rec	road; immediately began recovering huids. (PW: Spilled - 264 bbis., Kec 90 bbis., Lost - 1/4 bbis.)						
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached Attached	I hereby certify that the information given above is true and complete to	the best of my knowledge and und	lerstand that pursua	nt to NMOCD rules and				
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Tamala J. Robison OIL CONSERVATION DIVISION Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371								
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Tamala J. Robison Approved by Environmental Specialist: Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371								
federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Tamala J. Robison Approved by Environmental Specialist: OH Printed Name: Tamala J. Robison Approved by Environmental Specialist: Expiration Date: Title: Field Admin Support Approval Date: 8/14/2018 Expiration Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached								
OIL CONSERVATION DIVISION Signature: Tamala J. Robison Approved by Environmental Specialist: Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371 * Attache Additional Sheets If Nacessary Attached Improvemental Specialist								
Signature: Tamala J. Robison Approved by Environmental Specialist: Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371 * Attache Additional Sheets If Nacessary	federal, state, or local laws and/or regulations.							
Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371 * Attache Additional Sheets If Nacessary Attached Important		OIL CONSERVATION DIVISION						
Printed Name: Tamala J. Robison Approved by Environmental Specialist: Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371 * Attache Additional Sheets If Nacessary Attached Important	Signature: Tamala I Robison			1				
Printed Name: Tamala J. Robison International Support Title: Field Admin Support Approval Date: E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Date: 7/30/2018 Phone: 575-748-3371 * Attache Additional Sheets If Nacessary		Approved by Environmental Specialist:						
E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached Date: 7/30/2018 Phone: 575-748-3371 Attached	Printed Name: Tamala J. Robison							
E-mail Address: Tamala.Robison@dvn.com Conditions of Approval: Attached Date: 7/30/2018 Phone: 575-748-3371 Attached		0/1/2010						
Date: 7/30/2018 Phone: 575-748-3371 * Attached Additional Sheets If Nacessary	Title: Field Admin Support	Approval Date: 0/14/2016	Expiration Da	te:				
Date: 7/30/2018 Phone: 575-748-3371 * Attached Additional Sheets If Nacessary								
Date: 7/30/2018 Phone: 575-748-3371	E-mail Address: Tamala.Robison@dvn.com	Conditions of Approval:	Attached					
* Attach Additional Sheets If Necessary	D (7/00/0010 D) 575 740 2071							
nCH1822641737 IRP-5156								
	* Attach Additional Sneets II Necessary	nCH1822641737	RP-5156					

pCH1822642447

