Ms. Yu,

I have corrected the C-141 to show that it is a poly flow line associated with the well and the affected pasture was in square feet. Sorry for the inconvenience. Thanks and have a good day.

BRUCE BAKER

ENVIRONMENTAL TECHNICIAN SR direct 575-393-7106 ext 1523 | Cell 432-631-6982

APACHE CORPORATION 2350 W. MARLAND BLVD HOBBS , NM 88240

ApacheCorp.com | LinkedIn | Facebook | Twitter | StockTwits | YouTube

From: Yu, Olivia, EMNRD [mailto:Olivia.Yu@state.nm.us]
Sent: Friday, August 10, 2018 3:02 PM
To: Baker, Larry <Larry.Baker@apachecorp.com>; rmann@slo.state.nm.us
Subject: [EXTERNAL] RE: Initial C-141

Dear Mr. Baker:

Please clarify. Which injection flowline was affected by a fire? The GPS coordinates of the release location are for the wellhead. Also, did the fire impact 15,000 square feet of the pasture or 15,000 feet in length as written.

The 1RP for this incident is

					30-025-	
5155	8/10/2018	А	Apache	Warn State A/C 2 #9	03083	18S-35E-6M

Please remember to include this 1RP identifier to all communications. Also, please be advised that NMOCD recommends a completed site characterization/delineation report be reviewed or approved by NMOCD BEFORE any significant remediation work towards closure.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I <u>Olivia.yu@state.nm.us</u> 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Baker, Larry <Larry.Baker@apachecorp.com>
Sent: Friday, August 10, 2018 9:29 AM
To: Yu, Olivia, EMNRD <<u>Olivia.Yu@state.nm.us</u>>; rmann@slo.state.nm.us
Subject: Initial C-141

All,

Please find the attached initial C-141 for the flowline hydrocarbon fire that occurred at the Warn State A/C 2 # 9 on July 30, 2018. Please let me know if you have any questions or wish to discuss. Thanks and have a good weekend.

BRUCE BAKER

ENVIRONMENTAL TECHNICIAN SR direct 575-393-7106 ext 1523 | Cell 432-631-6982

APACHE CORPORATION 2350 W. MARLAND BLVD HOBBS , NM 88240 ApacheCorp.com | LinkedIn | Facebook | Twitter | StockTwits | YouTube

WARNING EXTERNAL EMAIL: This email is from an external source. Do not click links or open attachments without positive sender verification of purpose. Never enter Username, Password or sensitive information on linked pages from this email. If you are unsure about the message, please contact the ServiceDesk for assistance.

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company Apache Corporation Contact Bruce Baker Final Report Address 2350 W Marland Street, Hobbs, NM 88240 Telephone No. (432) 631-6982 Facility Type Facility Name Warn State A/C 2#9 Facility Type Oil Well Facility Type Surface Owner State Mineral Owner API No. 30-025-03083 Facility State

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
М	6	18S	35E	330'	FSL	913'	FWL	Lea

Latitude 32.7706146 Longitude -103.5024948

NATURE OF RELEASE

Type of Release Oil and Produced Water	Volume of Release 1/2 Barrel of oil and ¹ / ₂ a barrel of water	Volume Re	ecovered 0				
Source of Release poly flow line	Date and Hour of Occurrence 7/30/2018		Iour of Discovery at 1:30 a.m.				
Was Immediate Notice Given?	If YES, To Whom?						
By Whom? Jorge Rivera	Date and Hour 7/30/2018 at 3:23 p.m.						
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*							
Describe Cause of Problem and Remedial Action Taken.* Apache was notified by the Monument Volunteer Fire Department regarding the flow line fire. The line was isolated and the fire department extinguished the fire. The line was repaired.							
Describe Area Affected and Cleanup Action Taken.* The fire impacted approximately 15,000 square feet of pasture. The majority of the release fluid is thought to have been consumed in the fire.							
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.							
Signature: Bruce Baher	OIL CONSERVATION DIVISION						
Printed Name: Bruce Baker	Approved by Environmental Specialist:						
Title: Environmental Technician	Approval Date:	Expiration Date:					
E-mail Address: larry.baker@apachecorp.com	Conditions of Approval:		Attached				

* Attach Additional Sheets If Necessary