

**From:** Jennifer Knowlton  
**To:** [Mann, Ryan](#); [Yu, Olivia, EMNRD](#); [Hernandez, Christina, EMNRD](#)  
**Cc:** [Ron Hillman](#); ["Rocky Ray"](#); [kalpers@aecnm.com](mailto:kalpers@aecnm.com); [Herman Lucero](#)  
**Subject:** RE: C-141 for West Pearl Queen Injection  
**Date:** Thursday, June 14, 2018 8:37:51 AM  
**Attachments:** image001.png  
RE3768.pdf  
SLO Email Compression Facility Site Remediation.pdf

---

Ryan,

The coordinates were reversed on the RE Permit. The state form actually has W next to the latitude and N next to the longitude.

We will be taking GPS coordinates of the spill areas during the delineation phase and mapping that.

**Jennifer Knowlton, PE** | Regional Manager-Permian  
HRL Compliance Solutions, Inc.

main 575.616.7398 | mobile 505-238-3588

[Web](#) | [vCard](#) | [Map](#) | ☐ | ☐



Confidentiality Note: This email and any attachments are confidential and only for the use as authorized by HRL Compliance Solutions, Inc. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information. Permanently delete the e-mail and any attachments or copies.

---

**From:** Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>

**Sent:** Thursday, June 14, 2018 8:20 AM

**To:** 'Yu, Olivia, EMNRD' <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>; Jennifer Knowlton <[jknowlton@hrlcomp.com](mailto:jknowlton@hrlcomp.com)>; Hernandez, Christina, EMNRD <[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)>

**Cc:** Ron Hillman <[rhillman@aecnm.com](mailto:rhillman@aecnm.com)>; 'Rocky Ray' <[rocky@aecnm.com](mailto:rocky@aecnm.com)>; [kalpers@aecnm.com](mailto:kalpers@aecnm.com); [Herman Lucero](mailto:Herman.Lucero@hrlcomp.com) <[hllucero@hrlcomp.com](mailto:hllucero@hrlcomp.com)>

**Subject:** RE: C-141 for West Pearl Queen Injection

Good morning All,

I want to confirm we are all talking about the same location. The facility in question is located in T19S R35E NWNE. Not T18S as indicated by the initial c-141. Also I agree the provided coordinates are incorrect. 32.62274167, -103.47555556 seem to be closer to the facility in question.

Ryan Mann  
Remediation Specialist  
Field Operation Division  
(575) 392-3697  
(505) 699-1989  
New Mexico State Land Office  
2827 N. Dal Paso Suite 117  
Hobbs, NM 88240

---

**From:** Yu, Olivia, EMNRD [<mailto:Olivia.Yu@state.nm.us>]

**Sent:** Wednesday, June 13, 2018 1:47 PM

**To:** Jennifer Knowlton <[jknowlton@hrlcomp.com](mailto:jknowlton@hrlcomp.com)>; Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>; Hernandez, Christina, EMNRD <[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)>

**Cc:** Ron Hillman <[rhillman@aecnm.com](mailto:rhillman@aecnm.com)>; 'Rocky Ray' <[rocky@aecnm.com](mailto:rocky@aecnm.com)>; [kalpers@aecnm.com](mailto:kalpers@aecnm.com); [Herman Lucero](mailto:Herman.Lucero@hrlcomp.com) <[hllucero@hrlcomp.com](mailto:hllucero@hrlcomp.com)>

**Subject:** RE: C-141 for West Pearl Queen Injection

Ms. Knowlton:

No, the coordinates provided are incorrect. Both the RE permit and the topo image below reference the same location, which are the annotated revised GPS coordinates. NMSLO can verify.

Olivia


---

**From:** Jennifer Knowlton <[jknowlton@hrlcomp.com](mailto:jknowlton@hrlcomp.com)>  
**Sent:** Wednesday, June 13, 2018 1:30 PM  
**To:** Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>; Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>; Hernandez, Christina, EMNRD <[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)>  
**Cc:** Ron Hillman <[rhillman@aecnm.com](mailto:rhillman@aecnm.com)>; 'Rocky Ray' <[rocky@aecnm.com](mailto:rocky@aecnm.com)>; [kalpers@aecnm.com](mailto:kalpers@aecnm.com); Herman Lucero <[hlucero@hrlcomp.com](mailto:hlucero@hrlcomp.com)>  
**Subject:** RE: C-141 for West Pearl Queen Injection

Ms. Yu,

I think that the coordinate difference is just due reference system. See below.

Please note that we had to remove some contaminated soil in the removal of the pit to assess liner integrity. After removing the old compressor building, we also had to remove some soil as part of the sump removal. We will be delineating this site soon and submitting the work plan.



**Jennifer Knowlton, PE** | Regional Manager-Permian  
HRL Compliance Solutions, Inc.

main 575.616.7398 | mobile 505-238-3588

[Web](#) | [vCard](#) | [Map](#) | [□](#) | [□](#)

Confidentiality Note: This email and any attachments are confidential and only for the use as authorized by HRL Compliance Solutions, Inc. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information. Permanently delete the e-mail and any attachments or copies.

**From:** Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>  
**Sent:** Wednesday, June 13, 2018 1:05 PM  
**To:** Jennifer Knowlton <[jknowlton@hrlcomp.com](mailto:jknowlton@hrlcomp.com)>; Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>; Hernandez, Christina, EMNRD <[Christina.Hernandez@state.nm.us](mailto:Christina.Hernandez@state.nm.us)>  
**Cc:** Ron Hillman <[rhillman@aecnm.com](mailto:rhillman@aecnm.com)>; 'Rocky Ray' <[rocky@aecnm.com](mailto:rocky@aecnm.com)>; [kalpers@aecnm.com](mailto:kalpers@aecnm.com); Herman Lucero <[hlucero@hrlcomp.com](mailto:hlucero@hrlcomp.com)>

**Subject:** RE: C-141 for West Pearl Queen Injection

Dear Ms. Knowlton:

Please note that the GPS coordinates written on the C-141 do not match the latitude and longitude degrees provided on the RE-3768.

The 1RP for this incident is

<b>5090</b>	6/13/2018	A	Armstrong Energy Corp	West Pearl Queen Historic site		19S-35E-32B	unknown
-------------	-----------	---	-----------------------	--------------------------------	--	-------------	---------

Please remember to include this 1RP identifier to all communications. Also, please be advised that a release characterization/delineation workplan as detailed in the attachment must be approved by NMOCD BEFORE any remediation work.

Thanks,

Olivia Yu  
Environmental Specialist  
NMOCD, District I  
[Olivia.yu@state.nm.us](mailto:Olivia.yu@state.nm.us)  
575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

---



**From:** Jennifer Knowlton <[jknowlton@hrlcomp.com](mailto:jknowlton@hrlcomp.com)>  
**Sent:** Wednesday, June 13, 2018 8:22 AM  
**To:** Yu, Olivia, EMNRD <[Olivia.Yu@state.nm.us](mailto:Olivia.Yu@state.nm.us)>; Mann, Ryan <[rmann@slo.state.nm.us](mailto:rmann@slo.state.nm.us)>  
**Cc:** Ron Hillman <[rhillman@aecnm.com](mailto:rhillman@aecnm.com)>; 'Rocky Ray' <[rocky@aecnm.com](mailto:rocky@aecnm.com)>; [kalpers@aecnm.com](mailto:kalpers@aecnm.com); Herman Lucero <[hlucero@hrlcomp.com](mailto:hlucero@hrlcomp.com)>  
**Subject:** C-141 for West Pearl Queen Injection

Ms. Yu/Mr. Mann,

Attached please find a C-141 for the West Pearl Queen Injection Station. This will be a remediation/reclamation project. More details will be included in the work plan once we delineate the site more thoroughly.

Please feel free to contact me with any additional questions or concerns.

**Jennifer Knowlton, PE** | Regional Manager-Permian  
HRL Compliance Solutions, Inc.

main 575.616.7398 | mobile 505-238-3588  
[Web](#) | [vCard](#) | [Map](#) |  | 

---

Confidentiality Note: This email and any attachments are confidential and only for the use as authorized by HRL Compliance Solutions, Inc. If you receive this message in error or are not the intended recipient, you should not retain, distribute, disclose or use any of this information. Permanently delete the e-mail and any attachments or copies.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---