

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised June 10, 2003

|   |  |  |
|---|--|--|
| <b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) |  | WELL API NO. 30-025- <del>28423</del> 28483  |
| 1. Type of Well:<br>Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>   |  | 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input type="checkbox"/> |
| 2. Name of Operator<br>QUAY VALLEY, INC.  |  | 6. State Oil & Gas Lease No.<br>NM19447  |
| 3. Address of Operator P. O. BOX 10280<br>MIDLAND, TEXAS 79702  |  | 7. Lease Name or Unit Agreement Name<br>EXXON  |
| 4. Well Location<br>Unit Letter I : 1980 feet from the W line and 660 feet from the E line<br>Section 8 Township 26-S Range 32-E NMPM NM County LEA   |  | 8. Well Number<br>1  |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.)  |  | 9. OGRID Number<br>010461  |
|   |  | 10. Pool name or Wildcat<br>EAST MASON (DELAWARE)  |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

02-25-2004 SPOT 25 SKS. @4200' WOC & TAG @3980'.

02-27-2004 PERF @1500', COULD NOT PUMP IN SPOT 25 SKS. WOC & TAG @1,344'.

SPOT 25 SKS. 1,500' - 1,400'.

PERF@600' SQUEEZE 25 SKS. WOC & TAG @399'.


03-01-2004

PERF @50' SQUEEZE 30 SKS. TO SURFACE.

INSTALL P & A MARKER.

CIRC. MUD.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE PRESIDENT DATE 03/25/2004

Type or print name STELLA SWANSON

E-mail address:

Telephone No. (432) 687-4220

(This space for State use)

APPROVED BY [Signature] TITLE FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAR 30 2004

Conditions of approval, if any