Submit 3 Copies To Appropriate District Office	State of 1	State of New Mexico		Form C-103			
District I	Energy, Minerals and Natural Resources		Revised June 10, 2003				
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO	= -		
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION				30-041-20708		
District III	1220 South St. Francis Dr.			5. Indicate Type of Lease STATE FEE X			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505				0. 2.0.0	Cub Loube 110.		
	TEC AND DEDODTE ON	TWELLO		7 7 37	TT '. A		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				/. Lease Nam	e or Unit Agreement	Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			WILCOX TS				
PROPOSALS.) 1. Type of Well:				8. Well Number			
Oil Well X Gas Well Other					#3		
2. Name of Operator				9. OGRID Nu	ımber		
Yates Petroleum Corporation	1				025575		
3. Address of Operator				10. Pool name	or Wildcat		
	105 S. 4 th Street, Artesia, NM 88210				nahawk San Andres		
4. Well Location							
Unit Letter B : 33	0' feet from the	FNL	line and	1980' feet from	m the FEL	line	
Section 19	Township 7S	S Rang	ge 32E	NMPM ROOS	SEVELT County		
Section				-	SEVELT County		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
12 Check A	ppropriate Box to Inc	dicate N	oture of Notice	Donort or Oth	on Doto		
NOTICE OF INT	FNTION TO:	uicaic iv		BSEQUENT F			
	PLUG AND ABANDON	X	REMEDIAL WO		ALTERING CASI	NG 🗀	
_				_	_	_	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE D			RILLING OPNS.[_	PLUG AND ABANDONMENT	. 📙		
PULL OR ALTER CASING	MULTIPLE		CASING TEST	AND [
	COMPLETION		CEMENT JOB				
OTHER:			OTHER:				
13. Describe proposed or comple	ted operations. (Clearly	state all p	ertinent details, a	and give pertinent	dates, including estim	ated date	
of starting any proposed work	k). SEE RULE 1103. F	or Multipl	e Completions:	Attach wellbore dia	agram of proposed co	mpletion	
or recompletion.					31-123456		
Propose to P&A as follows:							
1) MIRU a WSU. Rig up safety trailer as necessary and ND wellhead, NU BOP. TOH w/ tubing.							
1) MIRU a WSU. Rig up sa	fety trailer as necessary	and ND w	ellhead, NU BO	P. TOH w/ tubing.			
2) RUWL company. RIH w	/ 4 ½" CIBP and set at 3	and ND w 5,920'. Du	rellhead, NU BOI ump 35' cement o	n plug. 🛮 🖔			
2) RUWL company. RIH w3) TIH w/ tubing & circulate	$4 \frac{1}{2}$ CIBP and set at 3 hole w/ 9.5# mud.	and ND w 3,920'. Du	rellhead, NU BOI			.001127	
2) RUWL company. RIH w3) TIH w/ tubing & circulate4) TOH w/ tubing laying do	/ 4 ½" CIBP and set at 3 hole w/ 9.5# mud. wn +/- 2,250' of tubing.	and ND w 3,920'. Du	vellhead, NU BOI ump 35' cement o	n plug. 🛮 🖔		10112737	
 2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying do 5) RUWL & shoot squeeze l 6) Spot 100' cement plug in 	/ 4 ½" CIBP and set at 3 thole w/ 9.5# mud. wn +/- 2,250' of tubing. noles at 1,728'. & out of casing from 1,7	3,920'. Du 728'-1.628	ump 35' cement o	n plug.	4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	01112797	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying dov 5) RUWL & shoot squeeze h 6) Spot 100' cement plug in 7) Spot 60' cement plug at si	4 4 ½" CIBP and set at 3 thole w/ 9.5# mud. wn +/- 2,250' of tubing. noles at 1,728'. & out of casing from 1,7 urface.	3,920'. Du 728'-1,628 -> ∑ Po	ump 35' cement on 35'. (Tag plug).	n plug.	NOTHED 224	.00112797	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying dov 5) RUWL & shoot squeeze b 6) Spot 100' cement plug in 7) Spot 60' cement plug at si 8) Cut off wellhead and insta	the hole w/ 9.5# mud. wn +/- 2,250' of tubing. holes at 1,728'. wout of casing from 1,7 urface. hall marker	728'-1,628	35' cement of the state of the	SSION MUST BE	NOTIFIED 224 OF	101112737	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying dov 5) RUWL & shoot squeeze h 6) Spot 100' cement plug in 7) Spot 60' cement plug at si	the hole w/ 9.5# mud. wn +/- 2,250' of tubing. holes at 1,728'. wut of casing from 1,7 urface. all marker.	728'-1,628	THE COMMI HOURS PRICE LEGINEGE	SSION MUST BE DR TO THE BE	NOTIFIED 224 OF	101112797	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying do 5) RUWL & shoot squeeze l 6) Spot 100' cement plug in 7) Spot 60' cement plug at si 8) Cut off wellhead and insta 9) Clean up and rip location.	* 4 ½" CIBP and set at 3 c hole w/ 9.5# mud. wn +/- 2,250' of tubing. holes at 1,728'. & out of casing from 1,7 urface. all marker. /DO CEM FROM 40 THIS IS FI	728'-1,628 → SPO • PLUG • PLUG • PESSIT 1	35' cement of the community of the commu	SSION MUST BE DR TO THE BE BERATIONS FOR	NOTIFIED 224 OF	103112737	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying dov 5) RUWL & shoot squeeze h 6) Spot 100' cement plug in 7) Spot 60' cement plug at st 8) Cut off wellhead and insta 9) Clean up and rip location. I hereby certify that the information at	which has been discussed as the state of the wide with the	728'-1,628 -> SPO ->	35' cement of the community of the commu	SSION MUST BE SERVED WIS FOR TO THE BEAUTION SERVED.	NOTIFIED 224 OF THE COMPAGE OF THE C	101112797	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying do 5) RUWL & shoot squeeze l 6) Spot 100' cement plug in 7) Spot 60' cement plug at si 8) Cut off wellhead and insta 9) Clean up and rip location.	which has been discussed as the state of the wide with the	728'-1,628 -> SPO ->	35' cement of the community of the commu	SSION MUST BE SERVED WIS FOR TO THE BEAUTION SERVED.	NOTIFIED 224 OF	4	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying do 5) RUWL & shoot squeeze h 6) Spot 100' cement plug in 7) Spot 60' cement plug at si 8) Cut off wellhead and insta 9) Clean up and rip location. I hereby certify that the information at SIGNATURE: Type or print name Su'Ann Rogers	which the whole w/9.5# mud. wh	728'-1,628 -> SPO PLUG	33. (Tag plug). THE COMM! HOURS PRICE PRICE HOURS St of my knowled	SSION MUST BE BEGIN TO THE BEGIN THE BEGIN TO THE BEGIN THE BEGIN TO T	ATE: 3/24/C	<u>.</u> 14. 48-1471	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying dov 5) RUWL & shoot squeeze h 6) Spot 100' cement plug in 7) Spot 60' cement plug at si 8) Cut off wellhead and insta 9) Clean up and rip location. I hereby certify that the information all SIGNATURE:	which the whole w/9.5# mud. wh	728'-1,628 -> SPO PLUG	33. (Tag plug). THE COMM! HOURS PRICE PRICE HOURS St of my knowled	SSION MUST BE BEGIN TO THE BEGIN THE BEGIN TO THE BEGIN THE BEGIN TO T	ATE: 3/24/C	<u>.</u> 14. 48-1471	
2) RUWL company. RIH w 3) TIH w/ tubing & circulate 4) TOH w/ tubing laying do 5) RUWL & shoot squeeze h 6) Spot 100' cement plug in 7) Spot 60' cement plug at st 8) Cut off wellhead and insta 9) Clean up and rip location. I hereby certify that the information at SIGNATURE: Type or print name Su'Ann Rogers	which the whole w/9.5# mud. wh	728'-1,628 -> SPO PLUG	33. (Tag plug). THE COMM! HOURS PRICE PRICE HOURS St of my knowled	SSION MUST BE BEGIN TO THE BEGIN THE BEGIN TO THE BEGIN THE BEGIN TO T	NOTHER 224 PROTECTION OF THE COMBS	<u>.</u> 14. 48-1471	

 WELL NAME: Wilcox "TS" #3
 Field: Tomahawk San Andres


 LOCATION:
 Unit B, Sec 19, T7S-32E 330' FNL & 1980' FEL
 Roosevelt County

 GL: 4442.1'
 ZERO:
 KB: 4452.1

 SPUD DATE: 8/12/95
 8/12/95
 COMPLETION DATE: 8/24/95

 COMMENTS: 30-005-63075
 30-005-63075

 BEFORE PTA



WELL NAME: Wilcox "TS" #3 Field: Tomahawk San Andres

LOCATION: Unit B, Sec 19, T7S-32E 330' FNL & 1980' FEL Roosevelt County

GL: 4442.1' ZERO: KB: 4452.1

COMPLETION DATE: 8/24/95

COMMENTS: 30-005-63075

AFTER PTA


SPUD DATE: 8/12/95

1

8 5/8" 24# 8R J-55	1678'
4 ½" 9.5# J-55 ST&C	4300'
<u> </u>	}

3325'

1678'



TD 4300'