

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-06934

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil / Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
CHEVRON USA INC

3. Address of Operator
15 SMITH ROAD, MIDLAND, TX 79705

4. Well Location

Unit Letter G : 1980' Feet From The NORTH Line and 1980' Feet From The EAST Line

Section 32 Township 21-S Range 37-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3457' GL

7. Lease Name or Unit Agreement Name
W.T. MCCOMACK

8. Well No.
5

9. Pool Name or Wildcat
PENROSE SKELLY GRAYBURG

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ DRILL DEEPER IN GRAYBURG

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-17-04: MIRU KEY #462. TAG & TAG CMT @ 71'. D/O CMT FR 71' TO 180'.

3-18-04: D/O HARD CMT FR 180-437.

3-19-04: TIH & ISOLATE TOP OF 6: CSG LEAK @ 350.

3-22-04: MIX & PUMP 212 SX CL C NEAT CMT @ 14.8 PPG 1.32 CU.FT./SX. CIRC CMT TO SURF. DISPL CMT TO 250' W/7 BBLS FW W/FINAL SQZ PRES OF 400 PSI.

3-23-04: TAG CMT @ 265. D/O CMT DN TO 464. STARTED PLUGGING OFF. UNPLUG BIT.

3-24-04: TAG @ 444. D/O BAD SPOT IN CSG @ 444. FALL THRU TO 464. D/O CMT DN TO 470'. TAG @ 464. D/O DN TO 480. D/O DN TO 526.


3-25-04: TAG @ 438. ROTATE THRU BAD SPOT DN TO 444. D/O CMT DN TO 674.

3-26-04: C/O 69' FILL. DRILL CMT FR 674-753.

3-29-04: TAG FILL @ 596'. D/O CMT TO 776. QUIT MAKING HOLE. D/O CMT FR 776-832.

3-31-04: RUN 2 7/8" TBG. RIG DOWN. CLEAN LOCATION. TURN WELL OVER TO PRODUCTION TO BE PLUGGED & ABANDONED DUE TO BAD 6" CSG.

FINAL REPORT



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist

DATE 4/5/2004

TYPE OR PRINT NAME Denise Leake

Telephone No. 915-687-7375

(This space for State Use)

APPROVED Hay W. Wink
CONDITIONS OF APPROVAL, IF ANY:

TITLE

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

APR 07 2004