
Submit 3 Copies To Appropriate District Office District 1  State of New Mo Energy, Minerals and Natu	- 0 C 100
District I Energy, IMINERALS and Natu 1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 811 South First, Artesia, NM 87210 OIL CONSERVATION	DIVISION 30-025-29766
District III 2040 South Pac	5 Indicate Type of Leace
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 8	
2040 South Pacheco, Santa Fe, NM 87505	16865
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR	DR SUCH Tonto, State 14
PROPOSALS.)	Tomo, State 14)
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator	8. Well No. 3
Nadel and Gussman Permian, L. L. C.	, p
3. Address of Operator	9. Pool name or Wildcat
601 North Marienfeld, Suite 508 Midland, Tx. 79701	Airstrip, N. (Bone spring)
4. Well Location E 1980 Nor	th 660 West
Unit Letter feet from the	
Section 14 Township 18S	
10. Elevation (Show whether D 4020' GL	R, RKB, RT, GR, etc.)
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND
PULL OR ALTER CASING  MULTIPLE	ABANDONMENT CASING TEST AND
COMPLETION	CEMENT JOB
OTHER:	OTHER:
12. Describe proposed or completed operations. (Clearly state all pe	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompilation.  THE COMMISSION MUST BE NOTIFIED 27	
<ol> <li>Notify NMOCD Hobbs office 48 hrs before starting wor</li> </ol>	HOURS PRIOR TO THE BEGINNING OF
<ol> <li>Notify NMOCD Hobbs office 48 hrs before starting wor</li> <li>MIRU PU check well for pressure.</li> </ol>	TA PLUCCING OPERATIONS FOR THE C-103 TO BE APPROVED.
3. ND well head NU BOP	
4. POH with production equipment	
5. MIRU wire line truck RIH and set CIBP @ 8650'. Cap w/ 30 ' cmt  6. TIH w/ tbg and test CIBP and csg to 500 psi and chart	
6. TIH w/ tbg and test CIBP and csg to 500 psi and chart 7. TOH, LD tbg and install dry hole tree	
8. RDMO pulling unit.	$\sqrt{2}$ $Q_2 \sim \sqrt{2}$
	24.25. A. S.
	\2 \\2\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
	12 No. 12
	best of my knowledge and belief.  Operations Engineer
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE & & M. Change TITLE	Operations Engineer
SIGNATURE & MC (Clarky_TITLE_	DATE 4/14/04
Type or print name Kem E. McCready	Telephone No. 432-682-4429
(This space for State use)	
APPPROVED BY Lay W. Wink TITLE DATE	
Conditions of approval, if any OC FIELD REPRESENTATIVE II/STAFF MANAGIAPR 2 0 2004	

## NADEL AND GUSSMAN PERMIAN

## Tonto 14 State #3

1980' FNL, 660' FWL, Unit E, Sec 14, T-18-S, R-34-E, Lea County, NM
API # 30 - 025 - 29766

Elev: 4020' GL, KB = NA



PBTD @ 9885


TD @ 10150'

## NADEL AND GUSSMAN PERMIAN

## Tonto 14 State #3

1980' FNL, 660' FWL, Unit E, Sec 14, T-18-S, R-34-E, Lea County, NM API # 30 - 025 - 29766

Elev: 4020' GL, KB = NA



TD @ 10150'