		*				
Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
District I	Energy, Minerals and Natural Resources			Revised June 10, 2003		
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-025-34781		
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Type of Lease		
1000 Rio Brazos Rd., Aztec, NM 87410		Santa Fe, NM 87505		STATE S FEE 6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM				6. State O	il & Gas Lease No.	
87505 SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS	CES AND REPORTS C			7. Lease N Hawkeye	Jame or Unit Agreement N 30 State	lame
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				0 11 11 11	1	
1. Type of Well: Oil Well Gas Well X Other			8. Well Number 1			
2. Name of Operator	يون دفع. مور دفع.			9. OGRID	Number 217817	
ConocoPhillip				10 D 1		
3. Address of Operator 4001 Pent Odesså, T	X 79762			Vacuum; N	ame or Wildcat Morrow	
4. Well Location						
Unit Letter J:::::::	1980 feet from the	South	line and	1970	feet from the <u>East</u>	line
Section 30	Township 17		lange 34-E	NMPM	County Lea	
	11. Elevation (Show v 4086' GL - 4104' KB			c.)		
12. Check A	ppropriate Box to In	ndicate N	Vature of Notice,	Report or	Other Data	
NOTICE OF INT	ENTION TO:		SUB	SEQUENT	TREPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	1	REMEDIAL WOR	•	ALTERING CASING	G 🗌
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI	LLING OPNS	. D PLUG AND ABANDONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AN CEMENT JOB	ND		
OTHER: Logging Runs		X	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion						
or recompletion.	\mathbf{k}). See RULE 1103.	For Multip	ple Completions: A	ttach wellbor	e diagram of proposed con	apletion
oraceomptetion.						
		:			х. 	
This is a notice of intent to conduct production logging runs on the above mentioned well. For your convenience, the recomended						
procedure and the wellbore diagram	m are attached.				A19202122233	
<i>.</i>				1.	and the second	\
					Sqqoy	3)
				13 14 15	UT TO	22
				\c \c	MOR Holy S	3/
				N.	E	/
					4534862	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE Starry	- finder	_TITLE_F	ISE/Regulatory Rep	oresentatibe	DATE03/16/20	04
Type or print name Stacey D. Linder	-	E-mail a	ddress:	×	Telephone No.	
(This space for State use)	- \	00	FIELD REPRESEN	TATIVE II/ST/	B	 4::1
APPPROVED BY Mary h	1. Wink	TITLE	- 1		APR 1	3 2004
Conditions of approval, if any:		· · · · ·		• • • • •		
	ಕ್ಷೆ ಮತ್ತು ಬಿಂದ ಬಿಂದ ಬಿಂದ ಬಿಂದ ಬಿಂದ ಬಿಂದ ಬಿಂದ ಬಿಂದ					- <u>16</u> 38 .

¢_

PROCEDURE: Hawkeye 30 State #1 Production Log

 MIRU ARC to conduct production logging runs. RU 10,000# lubricator and test lubricator to 1,800 Psig (1,000# above last max WHSIP). RIH with gauge ring to 13,300' to confirm access to perforations and sufficient rathole for logs. POOH. RIH with production logging tools and conduct three logging runs (30 fpm, 60 fpm and 90 fpm) up and down, through the Morrow perforation intervals. Correlate gamma ray to Schlumberger Compensated Neutron / Gamma Ray log (copy thru Morrow attached) dated Feb. 23, 2000. Lower tools in rathole and take the following stationary stops:

13,300' (below "Uncas" perfs / above "Hawkeye" perfs) 13,100' (above "Uncas" perfs)

NOTE: ALL DEPTHS ARE FROM 17' RKB

POOH with logging tools and confirm collection of data. RMDO ARC.

 E-mail or fax preliminary log section of spinner / temperature to Tim Harrington (<u>Tim.R.Harrington@conocophillips.com</u> or 832-486-2764) and Jack Lowder (<u>Jack.T.Lowder@ConocoPhillips.com</u> or 432-368-1330). Send completed copy of logs to Tim Harrington in Houston and Jack Lowder in Odessa.

Attachments: Well schematic

ConocoPhillips Company - Permian Basin Area 12/8/2003

	RKB 4103' GL 4086' 17 1/2" hole 13 3/8", 54.5#, J-55 Casing Set @ 400' 400 sx cmt. Circ 50 sx.	Lease & Well No. Well Category: Area: Subarea: API # Legal Description Spudded: Completed:	Two New Mexico Maljamar 30-025-34781
	11" hole 8 5/8", 32#, J-55 & S-80 Casing Set @ 4803'		0 13,452' - 13,470', 4 spf 2 13,137' - 13,143', 4 spf, zero deg
	1400 sx cmt. Circ 190 sx.		
	413 jts - 2-7/8", 6.5#, N-80 tubing (12,9 TOC @ ???'	92', bottom @ 13,010')	·
	Guiberson XL On-Off Tool w/ 2.313" "X" p Halliburton 10K Perma Latch packer @ 13 10', 2-7/8" N-80 pup jt	rofile @ 13,011' 5-1/2 3,016' 5-/12	ng Detail (Top-Bottom): 2" 64 jts, 17#, MAV-95 2678.52' 2" 183 jts, 17#, N-80, LT&C 7610.51' 2" 78 jts, 17#, MAV-95 3211.31'
	2.313" "X" nipple @ 13,027' Wireline Entry Guide/ EOT @ 13,028' 13,137'-13,143', 4 spf, 0 deg (4/30/02) Guiberson H.T. Magnum 15K pkr at 13,34	5-1/2 5-1/2 5-1/2	"Float Collar 1.15' "I jt, 17#, MAV-95 42.42' "Float Shoe 1.25' 13545.16' Casing above KB Setting Depth 13535.16'
	1 jt - 2-7/8", 6.5#, P-110 tubing (31.45') 2.313" 'XN' nipple @13,379' w/ W/L entry 9 13,452'-13,470' 4 spf Schlumberger Pivo 5-1/2", 17#, N-80 & MAV-95 @ 13,535'	guide on bottom	·
PBTD: TD:	13,492' 13,518'		

2

4