Submit 3 Copies To Appropriate District Office	State of New Energy, Minerals and			Form C-103 Revised June 10, 2003
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, winerars and	Natural Resources	WELL API N	
District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District W	OIL CONSERVAT 1220 South St. Santa Fe. NI			
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			K4105	WE AND A CONTRACT
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	SALS TO DRILL OR TO DEEPEN C	R PLUG BACK TO A	7 Lease Nam STATE L 8. Well Numb	e or Unit Agreement Name
1. Type of Well: Oil Well X Gas Well	Other			1
2. Name of Operator			9. OGRID Nu	umber 148967
Saga Petroleu 3. Address of Operator 415 W. V			10. Pool name	
Midland,	TX 79701		LANE ABO	
4. Well Location				
Unit Letter K	1980 feet from the S	line and	1980 feet	t from the <u>W</u> line
Section 2	Township 10S	Range 33E	NMPM	County LEA
	11. Elevation (Show whethe 4249.8'	er DR, RKB, RT, GR, etc	c.)	
NOTICE OF IN PERFORM REMEDIAL WORK	PLUG AND ABANDON	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AN CEMENT JOB OTHER:	SEQUENT R K	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT
13. Describe proposed or comp	oleted operations. (Clearly stat	e all pertinent details, an	id give pertinent	dates, including estimated date iagram of proposed completion
or recompletion. Have been attempting to establish on the chronological report that of cumulative costs to date are in et 3-12-04 Attempt to run MIT-TA. on Rod #299, LD 7475' of rods I 3-16-04 NDWH, NUBOP, POOF 3-17-04 Unload & rack 2-7/8" W 7/8" WS to 6000 psi above slips, tools 3-18-04 Continue to TIH w/tbg, a PU 10K, lose weight, POOH & r 3-19-04 Continue to TIH w/tbg, fish again, PU & lose fish, recato 5978', LD all 2-3/8" tbg in derric	n mechanical integrity to offici continues on the back of this fo xcess of \$45,000. Request exte Attempt to POOH w/rods, car DC:\$2950 H w/148 jts 2-3/8" tbg, parted, 'S, RU & RIH w/OS, w/3-1/16 TIH to fish @ 4608', catch fisl attempt to catch fish, can't catc ecover 4 jts 2-3/8" tbg, RIH to catch fish, gain 8K wt, SOOH, h & SOOH. Lose again, recatc	ally TA this well by the rm - have been working nsion to continue attemp n't due to paraffin, hot w collar looking up, prep t " grapple, bumper sub, j h, PU 10K, lose weight, h collar, POOH, change top of fish w/same tools lose fish w/43 stds out (March 26, 2004 g on the well sind pt to establish Mi tr csg, POOH, L o fish ars & 4 dc's. RU POOH, rec 1 jt ² grapple to fish (1/2 way) POOH	required date. As you can see be March 12, 2004 and IT for GA status. D all rods, discover pin break Phils Testers, hydrotest 2 Phils Testers, hydrotest 2 P
	ي جد الا الم الم الم الم الم الم الم الم الم		<u> </u>	
I hereby certify that the information SIGNATURE		the best of my knowled LE Production Analyst	ware as a set of the or	DATE 04/05/2004
		bhusband@	sagapetroleum.c	om Talanhana Na. (432)684-4293
Type or print name Bonnie Husband (This space for State use)	<u> </u>	ail address:	STATE MA	ANAGER
APPPROVED BY Conditions of approval, if any:	D. Wink TION	DFIELD REPRESENTAT	IVE II/STAPP IV	APR 1 5 2004

3-20-04	TIH w/full open top bushing OS w/2-19/32" grapple to catch pin looking up, catch pin,
	PU & RIH w/rods & 1-5/8" OS to fish rods. Catch rods, work to unseat pump for 1-1/2
3-23-04	hrs, lose weight, POOH w/rods, find barrel on OS is split SDFW.
3-23-04	RIH w/OS & rods, catch fish, attempt to unseat pump, work rods 30-mins, lose fish, can recatch, POOH, spring in OS bad, replace spring, RIH & catch fish, work to unseat pump
2 24 04	2-hrs, lose fish again, can't recatch, POOH, find OS bbl split
3-24-04	RIH w/OS & rods, catch fish, attempt to unseat pump, work rods 3-hrs, can't get pump loose. Backoff rods, have 5 pts, screw back onto rods, tighten rods up, backoff again,
	have 2 pts, screw back onto rods, return to attempt to unseat pump. Lose fish, POOH
	w/rods, change over to tbg, release TAC. POOH standing 2-7/8" WS back. Change
	elevators, slip dies, tong heads & BOP rams to 2-3/8". LD OS & 1 st fished it, continue to
	POOH, LD 2-3/8" tbg - 49 jts – get to rods, install valve on tbg. SION. Prep to continue
	to strip out Wed AM 3-24-04
3-25-04	Open BOP, backoff rods & POOH, LD all rods, recover pump valve rod. POOH w//45 jule 2-3/8" junk tbg. SD for rig repairs.
3-26-04	Continue to repair rig, POOH w/remainder of 2-3/8" tbg. RIH w/SN & 2-7/8" N-80 tbg,
	tag up @ 8968' w/288 jts in hole. RU Stearns, circ 218 bbls 2% KCL wtr w/soap to frac
	tank. Circ 168 bbls to frac tank. RD Stearns, open well to frac tank, flow back 40 BW in
	2-1/2-hrs. SI well. Total fluid rec 208 bbls
3-27-04	SITP vac, RU & RIH w/swab, IFL 900', swab back 64 bbls dirty wtr, FFL 3000' SDFW
3-30-04	SITP 0, RU & RIH w/swab, IFL 1800', swab back 89 bbls dirty wtr, FFL 3650', SION.
	Rec total 192 bbls.
3-31-04	SITP 0, RU & RIH w/swab, IFL 3000', swab back 68 bbls dirty wtr, FFL 3800', SION.
	Rec total 260 bbls.
4-01-04	SITP 0, RU & RIH w/swab, IFL 3600', swab back 72 bbls dirty wtr, FFL 4800', SION.
	Rec total 332 bbls.
4-02-04	SITP 0, RU & RIH w/swab, IFL 4300', swab back 81 bbls dirty wtr, FFL 5300', SION. Rec total 413 bbls.
4-03-04	SITP 0, RU & RIH w/swab, IFL 4800', swab back 85 bbls fluid, 3% oil cut, FFL 8200',
	Rec total 498 bbls fluid
	DC: \$1,816 CC: \$45,439

,

.

-