

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-33033
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Maljamar Grayburg Unit
8. Well Number 86
9. OGRID Number 022922
10. Pool name or Wildcat Maljamar Grayburg San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4218' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
The Wiser Oil Company

3. Address of Operator
P.O. Box 2568 Hobbs, New Mexico 88241 (505) 392-9797

4. Well Location

Unit Letter F: 2537 feet from the North line and 2603 feet from the West line

Section 4 Township 17S Range 32E NMPM Lea County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐


CASING TEST AND CEMENT JOB ☐

OTHER: Spot Lactol ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

01/16/04 MIRU Reeco Well Service. POH w/rods & pump. ND WH. RU BOP. POH w/2-7/8" tbg. LD BHA. RIH w/9 jts. 2-7/8" tbg., 2-7/8" x 5-1/2" AD-1 pkr., 2-7/8" spot control valve & 116 jts. 2-7/8" tbg. Tbg. @ 4050'. Pkr. @ 3870'. Spot 110 gals. Lactol (mineral spirits) across perfs. Shut in w/500# on tbg.

01/19/04 POH w/2-7/8" tbg. LD tools. RIH w/2-7/8" tbg. Tbg. @ 4266'. SN @ 4231'. RD BOP. NU WH. RIH w/rods & 1-1/2" x 16' pump. Hung well on. Left pumping to MGBU Battery. RDMO.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE March 29, 2004

Type or print name Mary Jo Turner E-mail address: mturner@wiseroil.com Telephone No. (505) 392-9797

(This space for State use)

APPROVED BY Gary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER
Conditions of approval, if any: APR 27 2004