Secretion Secr	Submit 3 Copies To Appropriate District Office District I	State of Ne Energy, Minerals and			Form C-103 Revised June 10, 2003
Sind Grand Ave., Artisis, NM 88210 1220 South St. Francis Dr. Santa Fe, NM 87505 S. Indicate Type of Lease STATE STATE	1625 N. French Dr., Hobbs, NM 88240	3.		WELL API NO.)-025-07542
Santa Fe, NM 87505 Sundrivative of Notice Tills (Notice Tills) Sundrivative of Notice Tills (Notice Tills) Sundrivative of Notice Tills (Notice Tills) Sundrivative of Notice Tills) Sundrivative of Notice Tills (Notice Tills) Sundrivative of Notice Tills) Sundrivative of Notice Tills) Sundrivative of Notice Tills (Notice Tills) Sundrivative of Notice Tills) Sundrivative of Tills)	1301 W. Grand Ave., Artesia, NM 88210 District III				
DO NOT USE THIS FORM POR PROPOSALS TO BRILL OF DEEPEN OR PLICE AND REPORTS ON WELLS	<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, N	NM 87505	6. State Oil & Gas Le	
RROPOSALS. 1. Type of Well: Oil Well	SUNDRY NOTI (DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A		it Agreement Name
2. Name of Operator Saga Petroleum LLC 3. Address of Operator 415 W Wall, Suite 1900 Midland, TX 79701 4. Well Location Unit Letter 1 : 1980	PROPOSALS.) 1. Type of Well:		-101) FOR SUCH		
148967 3. Address of Operator 41.5 W Wall, Suite 1900 10. Pool name or Wildcat Bowers 7 Rivers 4. Well Location 1. Letter I 1980 feet from the S line and 660 feet from the E line Section 32 Township 18S Range 38E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) Gr 3637 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: MIT for TA status ABANDONMENT COMPLETION CEMENT JOB OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Reference is made to April 14, 2004 Notice of Violation - Inspection No: iJDR0410552519 Well drid 7/1948. Completed 7/1948. 11" hole wis-5.8" 288 esg @ 300; cmtd w/300 sx, circ surf. 7" hole w/5-1/2" 15.5% esg @ 3124', cmtd w/1000 sx - TOC 350'. TD 3030', Well produced from open hole interval 3124-2192'. 4-21-04 sets test to 550 psi - held for 30 mins - good test - Chart attached - Did not call for witness, received verbal approval on 4-28-04 from Johnny Robinson that chart would be accepted. Saga wants to hold the wellbore for deepening to Queen, tentatively scheduled for the first quarter of 2005. This Approval of Temporary Abandonment Expires Abandonment Expires The Production Analyst Titure Product		Other			
4. Well Location Unit Letter I		m LLC		9. OGRID Number	148967
Unit Letter I : 1980 feet from the S line and 660 feet from the E line Section 32	3. Address of Operator 415 W Wall, Suite 1900 Midland, TX 79701			· · · · · · · · · · · · · · · · · · ·	
Section 32 Township 18S Range 38E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	4. Well Location				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) Gr 36377	Unit Letter I :_	1980 feet from the S	line and	feet from the	ne E line
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: MIT for TA status MIT for TA status	Section 32	11. Elevation (Show wheth			ounty Lea
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. ALTERING CASING ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: MIT for TA status 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Reference is made to April 14, 2004 Notice of Violation - Inspection No: iJDR0410552519 Well drid 7/1948 & completed 7/1948. 11" hole w/8-5/8" 28# csg @ 300', cmtd w/300 sx, circ surf. 7" hole w/8-5/8" 28# csg @ 300', cmtd w/1000 sx - TOC 350'. TD 3030', Well produced from open hole interval 3124'-2192'. 4-21-04 set RBP @ 3050', RU Key, load hole w/FW, press test csg to 500 psi, test good, Catch & release RBP, POOH w/same, PU CIBP & RIH, set CIBP @ 3050', Load csg & circ 60 bbls pkr fluid dwn csg. POOH, LD all 2-3/8" 4.6# J55 EUE tbg. 4-22-04 press test to 550 psi - held for 30 mins - good test - Chart attached - Did not call for witness, received verbal approval on 4-28-04 from Johnny Robinson that chart would be accepted. Saga wants to hold the wellbore for deepening to Queen, tentatively scheduled for the first quarter of 2005. This Approval of Temporary Abandonment Expires THE Production Analyst	12 Check A		ata Natura of Natica	Penart or Other Dat	to
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: COMPLETION CEMENT JOB OTHER: MIT for TA status I3. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Reference is made to April 14, 2004 Notice of Violation - Inspection No: iJDR0410552519 Well drid 7/1948. completed 7/1948. 11" hole w/8-5/8" 28# csg @ 300', cmtd w/300 sx, circ surf. 7" hole w/5-1/2" 15.5# csg @ 3124', cmtd w/1000 sx - TOC 350'. TD 3030', Well produced from open hole interval 3124'-2192'. 4-21-04 set RBP @ 3050', RU Key, load hole w/FW, press test csg to 500 psi, test good, Catch & release RBP, POOH w/same, PU CIBP & RIH, set CIBP @ 3050', Load csg & circ 60 bbls pkr fluid dwn csg. POOH, LD all 2-3/8" 4.6# J55 EUE tbg. 4-22-04 press test to 550 psi - held for 30 mins - good test - Chart attached - Did not call for witness, received verbal approval on 4-28-04 from Johnny Robinson that chart would be accepted. Saga wants to hold the wellbore for deepening to Queen, tentatively scheduled for the first quarter of 2005. This Approval of Temporary 4/22/04 The Production Analyst THE Production Analyst	NOTICE OF IN	ΓΈΝΤΙΟΝ ΤΟ:	SUB	SEQUENT REPOR	T OF:
PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: OTHER: MIT for TA status 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Reference is made to April 14, 2004 Notice of Violation - Inspection No: iJDR0410552519 Well drid 7/1948 & completed 7/1948. 11" hole w/8-5/8" 28# csg @ 300', cmtd w/300 sx, circ surf. 7" hole w/8-5/8" 28# csg @ 3124', emtd w/1000 sx - TOC 350'. TD 3030', Well produced from open hole interval 3124'-2192'. 4-21-04 set RBP @ 3050', RU Key, load hole w/FW, press test csg to 500 psi, test good, Catch & release RBP, POOH w/same, PU CIBP & RIH, set CIBP @ 3050', Load csg & circ 60 bbls pkr fluid dwn csg. POOH, LD all 2-3/8" 4.6# J55 EUE tbg. 4-22-04 press test to 550 psi - held for 30 mins - good test - Chart attached - Did not call for witness, received verbal approval on 4-28-04 from Johnny Robinson that chart would be accepted. Saga wants to hold the wellbore for deepening to Queen, tentatively scheduled for the first quarter of 2005. This Approval of Temporary 4/22/04 Thereby certify that the information above is true and complete to the best of my knowledge and belief.	TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Reference is made to April 14, 2004 Notice of Violation - Inspection No: iJDR0410552519 Well drld 7/1948 & completed 7/1948. 11" hole w/8-5/8" 28# csg @ 300', cmtd w/300 sx, circ surf. 7" hole w/5-1/2" 15.5# csg @ 3124', cmtd w/1000 sx - TOC 350'. TD 3030', Well produced from open hole interval 3124'-2192'. 4-21-04 set RBP @ 3050', RU Key, load hole w/FW, press test csg to 500 psi, test good, Catch & release RBP, POOH w/same, PU CIBP & RIH, set CIBP @ 3050', Load csg & circ 60 bbls pkr fluid dwn csg. POOH, LD all 2-3/8" 4.6# J55 EUE tbg. 4-22-04 press test to 550 psi - held for 30 mins - good test - Chart attached - Did not call for witness, received verbal approval on 4-28-04 from Johnny Robinson that chart would be accepted. Saga wants to hold the wellbore for deepening to Queen, tentatively scheduled for the first quarter of 2005. This Approval of Temporary 4/22/60 This Approval of Temporary 4/22/60 This Production Analyst	PULL OR ALTER CASING		•		ANDONMENT
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Reference is made to April 14, 2004 Notice of Violation - Inspection No: iJDR0410552519 Well drld 7/1948 & completed 7/1948. 11" hole w/8-5/8" 28# csg @ 300', cmtd w/300 sx, circ surf. 7" hole w/5-1/2" 15.5# csg @ 3124', cmtd w/1000 sx - TOC 350'. TD 3030', Well produced from open hole interval 3124'-2192'. 4-21-04 set RBP @ 3050', RU Key, load hole w/FW, press test csg to 500 psi, test good, Catch & release RBP, POOH w/same, PU CIBP & RIH, set CIBP @ 3050', Load csg & circ 60 bbls pkr fluid dwn csg. POOH, LD all 2-3/8" 4.6# J55 EUE tbg. 4-22-04 press test to 550 psi - held for 30 mins - good test - Chart attached - Did not call for witness, received verbal approval on 4-28-04 from Johnny Robinson that chart would be accepted. Saga wants to hold the wellbore for deepening to Queen, tentatively scheduled for the first quarter of 2005. This Approval of Temporary Abandonment Expires I hereby certify that the information above is true and complete to the best of my knowledge and belief.	OTHER:		OTHER: MIT for	TA status	X
Abandonment Expires 4/240 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE 1/2004 10 1/28/2004	of starting any proposed wo or recompletion. Reference is made to April 14, 20 Well drld 7/1948 & completed 7/1 11" hole w/8-5/8" 28# csg @ 300' 7" hole w/5-1/2" 15.5# csg @ 312 Well produced from open hole int 4-21-04 set RBP @ 3050', RU Ke CIBP & RIH, set CIBP @ 3050', Load csg 4-22-04 press test to 550 psi - held Did not call for witness, received signs.	rk). SEE RULE 1103. For 104 Notice of Violation - Insp. 948. , cmtd w/300 sx, circ surf. 4', cmtd w/1000 sx - TOC 3: erval 3124'-2192'. y, load hole w/FW, press test. & circ 60 bbls pkr fluid dwn. I for 30 mins - good test - Chyerbal approval on 4-28-04 f	Multiple Completions: A rection No: iJDR0410552 50'. TD 3030', c csg to 500 psi, test good ccsg. POOH, LD all 2-3/start attached - from Johnny Robinson the	ttach wellbore diagram of the state of the s	POOH w/same, PU
SIGNATURE ADMINIO TOTAL Production Analyst DATE 04/28/2004			This Abar	Approval of Temp adonment Expires	orary 4/22/00
SIGNATURE Sornie Souldand TITLE Production Analyst DATE 04/28/2004 Type or print name Bonnie Husband E-mail address: DATE 04/28/2004 bhusband@sagapetroleum.com E-mail address: DAMAY 1 1 2004	I hereby certify that the information a	above is true and complete to	the best of my knowledg	ge and belief.	
Type or print name Bonnie Husband E-mail address: E-mail address: APPPROVED BY APPPROVED BY APPROVED BY DAMAY 1 1 2004	SIGNATURE 130nnie	Kustand TIT	LE Production Analyst	D	ATE_04/28/2004
APPPROVED BY AND THE REPRESENTATIVE II/STAFF MANY 1 1 2004	Type or print name Bonnie Husband	E-n	bhusband@ nail address:	sagapetroleum.com	one No. (432)684-4293
Conditions of approval, if any:	APPPROVED BY	I while of the	e representative IV	STAFF MAIO	MAY 1 1 2004

