Submit 3 Copies To Appropriate District Office	State of New Me	exico	Form C-103
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-11668
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE S
District IV	Santa Fe, NWI 8/303		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)			B.M. Justis "A"
1. Type of Well:			
Oil Well Gas Well Other Injection			
2. Name of Operator Bettis, Boyle & Stovall			8. Well No. #002
3. Address of Operator			9. Pool name or Wildcat
P.O. Box 1240, Graham, Texas 76450			Jalmat Tansill Yates 7 Rivers
4. Well Location			
Unit Letter H : 1980 feet from the North line and 660 feet from the Esst line			
9	Tananahin 25 C	Damas 27 E	NIMPM County Los
Section 20 Township 25-S Range 37-E NMPM County Lea 10. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3,056' GR			
11. Check Ar	propriate Box to Indicate N	ature of Notice, F	Report or Other Data
NOTICE OF INT	. .		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG AND BANDONMENT	
	MULTIPLE COMPLETION	CASING TEST ANI CEMENT JOB	
OTHER:	П	OTHER:	1 1 3 3 1 1 3 1 1 1 1 1 1 1 1 1 1
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of			
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or			
recompilation.			
04/40/04 ##			
04/19/04 Monday Notified OCD, Buddy Hill. MIRU Triple N rig #23 and plugging equipment. Dug working pit. ND wellhéad, เป็น BOP. RIH w/			
23/8" workstring tog and tagged CIBP @ 2,949'. RU cementer and circulated hole w/ mud, pumped 25 sx C cmt @ 2,949'.			
POOH w/ tbg. RIH w/ wireline and tagged plug @ 2,760'. POOH w/ wireline. RIH w/ tbg to 2,630' and pumped 25 sx C cmt.			
POOH to 1,273' and pumped 25 sx C cmt. RIH w/ wireline and perforated @ 350'. POOH w/ tbg, SDFN.			
04/20/04 Tuesday			
RIH w/ 7" packer and set @ 200'. Pressured up to 1,000 psi and held. Notified OCD, Gary Wink. RIH and pumped 80 sx C			
cmt 350' to surface. RDMO.			
Cut off wellhead and anchors, capped well, installed marker. Backfilled pit and cellar.			
I hereby certify that the information ab	oove is true and complete to the h	est of my knowledge	and helief
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TO THE	TITLE_	engineer	DATE 04/28/04
U			
	Newman, P.E. Triple N	Services, Inc.	Telephone No. 432-687-1994
(This space for State use)			
APPPROVED BY Laus W	Wink TITLED R	EPRESENTATIVE II	STAFF MANAGER MAY 1 1 2004
Conditions of approval, if any:			THE THE PERSON NAMED IN TH