

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-025-06303
<b>1. Type of Well:</b> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Injector		<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>2. Name of Operator</b> Chevron USA Inc		<b>6. State Oil &amp; Gas Lease No.</b>
<b>3. Address of Operator</b> 15 Smith Rd, Midland, TX, 79705		<b>7. Lease Name or Unit Agreement Name:</b> Eunice Monument South Unit
<b>4. Well Location</b> Unit Letter <u>C</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>31</u> Township <u>20-S</u> Range <u>37-E</u> NMPM Lea County		<b>8. Well No.</b> 136
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b>		<b>9. Pool name or Wildcat</b> Eumont Monument Grayburg San Andres

<b>11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data</b>	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/> Replug <input type="checkbox"/>

**12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- Set 5 1/2" CIBP at 3680, spot 25sx, plug from 3680-3500 (Grayburg - San Andres) Tag at 3472.
- Displace hole w/MLF 9.5# Brine w/12.5# gel P/BBL.
- Perf 4 holes at 2600, unable to sqz, spot 35sx, plug from 2647-2400 (B-Salt, Yates) Tag at 2397.
- Perf 4 holes at 1200, sqz 50 sx from 1200-1000 (7 5/8 Shoe, T-Salt) Tag at 982.
- Perf 4 holes at 250, Circ cmt from 250-Surf w/160sx (10 3/4 Shoe) Tag at Surf.
- Install dry hole marker 5-4-04.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE Field Supervisor/Sunset DATE 5/4/04  
Type or print name Jimmy Bagley Telephone No. (432) 561-8600

APPROVED BY Glenn W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE MAY 13 2004  
Conditions of approval, if any: