State Of New Mexico

Form C-103 Revised March 25, 1999

District I	E	inergy, Mine	rais, and	Naturai Resou	ırces	_	
1625 N. French Drive., Hob	bs, NM 88240		ICEDVAT		.1	Well API	
District II	M 00040		0 South F	ION DIVISION	V		-025-24580
1301 W. Grand, Artesia, N	√1 88210		ita Fe, NN			State X	e Type Of Lease
District III		San	la I C, INIV	1 07303		State	
1000 Rio Brazos Rd., Azteo	; NM 87410					6 State (Oil and Gas Lease No.
District IV	a Ea NM 97505						7990
2040 South Pacheco, Santa		ND PEDOPTS	ON WELL	<u> </u>			Name Or Unit Agreement
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A							Name of one Agreement
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							
Type Of Well:	VOII. 002 711 210/11	J	(, , , , , , , , , , , , , , , , , , ,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	,	Jo	ANNIE STATE
Oil Well X	Gas Well Oth	er SWD					
<u> </u>	ســا ر						
Name Of Operator						8. Well N	lo.
Ray Westall Operating							5
Address Of Operator							lame Or Wildcat
	P.O. Box 4 - Loc	o Hills, New	Mexico 88	3255		VACUUM	GRAYBURG SAN ANDRES
Well Location							
_	4.650	- NORTH	1	1000 5 15	W	JECT	
Unit Letter F:	1650 Feet From	The NORTH	Line And	1980 Feet From	mine	Line	
	- ·· 100		34E	NIMPM Cours	I	EA	
Section 8	Township 18S	Range 10. Elevation		NMPM Count her DR, RKB, RT, GR	-7	LA	
		4063 GR	(Onow which	101 511, 1115, 111, 51	1, 001.7	* 1	
	11. Check Th		x To Indicate	Nature Of Notice, R	Report Or (Other Data	
NOTICE (OF INTENTION TO:		1	SUBSEQUEN			
Remedial Work	Plug And Abandon		Remedial W	ork		Alter Casing	
		_					
Temporarily Abandon	Change Plans		Commence	Drilling OPNS.		Plug and Abandon	ment
	_	_		A			
Pull Or Alter Casing	Multiple Completion		Casing Test	and Cement Job	Ш		
			l				
Other			Other:				L
		Olera de este de ellera	atia ant deteile	and sive nestingst de	etos includ	ing actimated date	of starting any
	or completed operations. (6						Or starting any
proposed work). St.	ERULE 1103. For Multip	le Completions. Al	lacii wellbole	diagram of proposed	compiction	r or recompletion.	
05/07/04	CURRENT CONDIT	LION					
03/07/04	TUBING TOP @ 27						2005
	DROPPED TUBING		NG OUT OF	HOLE			12 13 14 15 16 17 20
	ASAP-WILL MOVE				REMOV	E TUBING AND	
	START PRODUCIN					6	
	JIANI INODUCIN	io well non	•			/ 🕸	
						87	Why "IED
						(10)	, Jrins
						/ 60	Hr Hopp
						/c2	1
						/4	10 -03/
							46.05.829201gg0
,							
I horoby portify that the int	formation above is true an	complete to the	best of my kno	wledge and helief			
	. , 9 . /	`			Sacrata	n/	05/10/04
Signature	w My	ish _	Title	Production S	secretar	y Date	00/10/04
-	· //						(EOE) (77 0070
Type Or Print Name:	Willie English					relephone No.	(505) 677-2370

Type Or Print Name: (THIS SPACE FOR STATE USE)

Conditions Of Approval If Any: