State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL CONSERVATION DIVISION						
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St.			WELL API NO.	WELL API NO. 30-025-30204		
DISTRICT II	Santa Fe, NM 87505			5 Indicate Type	5. Indicate Type of Lease		
811 S. 1st Street, Artesia, NM 88210				FED FED	-	X FEE	
DISTRICT III				6. State Oil & G		<u> </u>	
1000 Rio Brazos Rd, Aztec, NM 87410							
SUNDRY NOTICES AND REPORTS ON WELLS							
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name of	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)				NORTH HOP	NORTH HOBBS (G/SA) UNIT		
1. Type of Well:	A C-101 FOR SUCH PROPOSALS.		, BS (G/SA) UI	NII			
Oil Well	Gas Well Other INJECTOR			Section 31	Section 31		
2. Name of Operator		8. Well No.	322				
Occidental Permian, LTD	H.B. (B)						
3. Address of Operator	ODDG NN4 00040				Wildcat	HOBBS (G/SA)	
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 4. Well Location							
	Feet From The NORTH	T Time and	1500	F4 F Th-	E A CE	T :	
Unit Letter G: 2480	Feet From The NORTH	Line and	1509 I	Feet From The	EAST	Line	
Section 31	Township 18S			8E NMPN	Л <i>потитите</i>	LEA County	
	10. Elevation (Show whether I	DF, RKB, RT GR, e	tc.)	·			
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK	PLUG AND ABANDON	☐ REMEDIA	AL WORK		ALTERING C	ASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMEN	ICE DRILLING C	OPNS.	PLUG & AB/	ANDONMENT	
PULL OR ALTER CASING							
OTHER:							
Sq2 and rest est appear out a finance zone							
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.							
 RUPU. Pull injection equipment. Sqz csg leak and perfs between 4110 and 4180'. 							
3. Re-Perforate the San Andres zone (4155'-58'), 1 JSPF; (4161' - 67'), 1 JSPF; and (4224' - 32'), 2 JSPF. Total of 25 holes							
4. Stimulate new San Andres perfs w/925 g 15% NEFE HCL acid.							
5. RIH w/5.5" Guiberson pc G-6 pkr and set @4050', XL on/off tool w/1.875 ss "F" nipple.							
 6. 131 jts 2-7/8" Duoline tbg. Bottom of tbg @4050'. 7. Circ csg w/90 bbl pkr fluid. Test csg to 580 psi for 30 min and chart for the NMOCD. 							
7. Circ csg w/90 bbl pkr fluid. Test csg to 580 psi for 30 min and chart for the NMOCD. 8. NU wellhead. RDPU. Clean Location. Well returned to injection 04/30/2004 Rig up Date: 04/16/2004							
Well returned to injection 04/30/2004					268[] 總	ಪ	
				13	の日産	£/	
Rig up Date: 04/16/2004 Rig Down Date: 04/29/2004					0		
Rig Down Date. 04/29/2004					·	3/ 12 ×	
					ECTOSS.		
I hereby certify that the information above is	true and complete to the best of my	knowledge and bel	lief.				
SIGNATURE X Shut	L. Writ	TITLE	Workover (Compl Specialist	DATE	05/05/2004	
TYPE OR PRINT NAME Robert Gi	lbert			TEL.	EPHONE NO.	505/397-8206	
(This space for State Use)	1.1		٨ ٨	SE MANAGER			
(This space for State Use) APPROVED BY CONDITIONS OF APPROVALUANY: OC FIELD REPRESENTATIVE II/STAFF MANAGEM DATE MAY 1 4 2004							
CONDITIONS OF APPROVALIDANY:	OC FIEL	D KEI KHYEE			DATE		

