

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-34281

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Theodore Anderson

8. Well No.

14

9. Pool name or Wildcat

Monument ABO - SE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Chevron USA Inc

3. Address of Operator

15 Smith Rd, Midland, TX, 79705

4. Well Location

Unit Letter A : 660 feet from the North line and 810 feet from the East line

Section 17 Township 20-S Range 37-E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE
COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND
ABANDONMENT ☒

CASING TEST AND
CEMENT JOB ☐

OTHER: ☐ Replug ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2" CIBP at 6975, spot 25sx, plug from 6975-6800 (ABO), Tag at 6751.
2. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL.
3. Spot 25sx, plug from 5118-4878 (Glorieta).
4. Spot 25sx, plug from 3611-3371 (Queen).
5. Cut 5 1/2" csg at 2514, unable to pull or sqz, spot 40sx, plug from 2575-2300 (8 5/8 Shoe, B-Salt), Tag at 2198.
6. Perf 4 holes at 1300, sqz w/55sx from 1300-1100 (T-Salt), Tag at 1042.
7. Perf 4 holes at 450 (11 3/4 Shoe), Circ cmt 5 1/2 x 8 5/8 csg w/132sx, Tag at Surf.
8. Install dry hole marker 4-26-04.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Field Supervisor/Sunset DATE 4/26/04

Type or print name Jimmy Bagley

Telephone No. (432) 561-8600

(This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER

Conditions of approval, if any:

DATE MAY 14 2004