Submit 3 Copies To Appropriate District	State of New	w Mexico		Form C-103
Office District I	Energy, Minerals and Natural Resources		March 4, 2004	
1625 N. French Dr., Hobbs, NM 88240	<u> </u>		WELL API NO.	
District II	OIL CONSERVAT	NOISINIA MOL	30-025-36544	
1301 W. Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease	
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St.		STATE 🔀 F	EE 🗌
District IV	Santa Fe, N	M 87505	6. State Oil & Gas Lease N	No.
1220 S. St. Francis Dr., Santa Fe, NM				
87505	ES AND REPORTS ON W	ELIC	7 Lagge Name on Unit Age	roomant Nama
(DO NOT USE THIS FORM FOR PROPOS.			7. Lease Name or Unit Agr	reement Name
DIFFERENT RESERVOIR. USE "APPLICA			State D	
PROPOSALS.)	,	,	State R	
1. Type of Well:			8. Well Number	
Oil Well Gas Well	Other		4	
2. Name of Operator			9. OGRID Number	
Devon Energy Production Comp	anv. LP		6137	
3. Address of Operator			10. Pool name or Wildcat	
20 N. Broadway, Ste 1500 Okla	homa City OK 73102-8260)	Osudo; Morrow, West (Gas)	
4. Well Location	Homa City, Ok 75102 0200		Osado, Monto, Mest (G	
4. Well Location				
Limit Latton D	1000feet from theN	lawth line and	1790 fact from the	East line
Unit LetterB	1000leet from theN	inie and	17801eet from the	Lastinic
Soction 1	Township 21S	Range 34E	NMPM Lea	County
Section 1	11. Elevation (Show whether			County
是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	3675 GL			
Pit or Below-grade Tank Application (For			ed)	
Pit Location: UL BSec1_Twp_215	SRng_34E Pit typeDri	llingDepth to Groundwat	er>100'Distance from near	rest fresh water
well_>1000'				
Distance from nearest surface water >10	00 Below-grade Tank Location	1 UL Sect Tw	pRng;	
Distance from nearest surface water_>10			PRng;	TC
Distance from nearest surface water_>10			$\underline{\Gamma}$ Rng; $\underline{\Gamma}$ 2^{13} 14 15 7	1677/20
_			PRng; \(\begin{align*} \Gamma & \text{N} & \te	1677/87
feet from theline and	feet from theline	EXISTING PI	Γ (2) 13 14 15 7	C/ \
feet from theline and	feet from theline	EXISTING PI	Report or Other Data	20.
feet from theline and	feet from theline	EXISTING PI	Report or Other Dataly	©F : 12
feet from theline and	ppropriate Box to Indicate TENTION TO:	e EXISTING PIC ate Nature of Notice,	Report or Other Dataly	©F : 12
feet from theline and	ppropriate Box to Indicate TENTION TO:	ate Nature of Notice, SUE REMEDIAL WOR	Report or Other Dataly SSEQUENT REPORT, KK OCCUSER	ØF: 18
feet from theline and	ppropriate Box to Indica FENTION TO: PLUG AND ABANDON	ate Nature of Notice, SUE REMEDIAL WOR	Report or Other Dataly SSEQUENT REPORT, KK AND PRICE OF SERVICES	ØF: \$ ØF casing □ ND & □
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON	ppropriate Box to Indica FENTION TO: PLUG AND ABANDON CHANGE PLANS	ate Nature of Notice, SUB REMEDIAL WOR	Report or Other Dataly SEQUENT REPORT, KK AGERIC OCO OLIVIES ALBANDO ABANDO	ØF: ØG CASING U
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK	ppropriate Box to Indica FENTION TO: PLUG AND ABANDON CHANGE PLANS	ate Nature of Notice, SUB REMEDIAL WOR COMMENCE DR CASING TEST A	Report or Other Data SSEQUENT REPORT, OCO STATE OF SERVICE ABANDO	ØF: ØG CASING U
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON	ppropriate Box to Indica FENTION TO: PLUG AND ABANDON CHANGE PLANS	ate Nature of Notice, SUB REMEDIAL WOR	Report or Other Dataly SEQUENT REPORT, KK AGERIC OCO OLIVIES ALBANDO ABANDO	ØF: ØG CASING U
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	ppropriate Box to Indica FENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	ate Nature of Notice, SUB REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB	Report or Other Dataly SEQUENT REPORT, KK AGERIC OCO OLIVIES ALBANDO ABANDO	ØF: ØG CASING U
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	ppropriate Box to Indica FENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	EXISTING PICAL SUB- REMEDIAL WORL COMMENCE DR CASING TEST A CEMENT JOB OTHER:	Report or Other Dataly SSEQUENT REPORT, RK COCOS ILLING OPNS: PLUG A ABANDO ND ABANDO ND	ØF: NG CASING
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	ppropriate Box to Indicate Plug AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	EXISTING PICAL ACTION OF THE PICK SUB-REMEDIAL WORD COMMENCE DR. CASING TEST ACEMENT JOB OTHER:	Report or Other Dataly SEQUENT REPORT, RK AGERIC OCOS ILLING OPNS PLUG A ABANDO ND COS 67 3	ØF: ØF: ØF CASING □ ND □ ONMENT
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work.	ppropriate Box to Indicate Plug AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	EXISTING PICAL ACTION OF THE PICK SUB-REMEDIAL WORD COMMENCE DR. CASING TEST ACEMENT JOB OTHER:	Report or Other Dataly SSEQUENT REPORT, RK COCOS ILLING OPNS: PLUG A ABANDO ND ABANDO ND	ØF: ØF: ØF CASING □ ND □ ONMENT
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion.	ppropriate Box to Indicate Plug AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	EXISTING PICAL ACTION OF THE PICK SUB-REMEDIAL WORD COMMENCE DR. CASING TEST A CEMENT JOB OTHER:	Report or Other Dataly SEQUENT REPORT, RK AGERIC OCOS ILLING OPNS PLUG A ABANDO ND COS 67 3	ØF: ØF: ØF CASING □ ND □ ONMENT □ ing estimated date
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole	ppropriate Box to Indicate For Ton To: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly stack). SEE RULE 1103. For Markening Completed C	EXISTING PICAL ACTION OF THE PICK SUB REMEDIAL WORLD COMMENCE DR CASING TEST A CEMENT JOB OTHER:	Report or Other Dataly SEQUENT REPORT, KK AND PLUG A ABANDO ABANDO	OF: ND □ ONMENT ing estimated date oposed completion
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole 03/06/04 TD 17 ½" hole @ 1950".	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS COMPLETION eted operations. (Clearly stack). SEE RULE 1103. For Mark Mark 13 3/8" 54.5# K55	EXISTING PICAL ACTION OF THE PICK SUB REMEDIAL WORLD COMMENCE DR CASING TEST A CEMENT JOB OTHER:	Report or Other Dataly SEQUENT REPORT, KK AND PLUG A ABANDO ABANDO	OF: ND □ ONMENT ing estimated date oposed completion
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS COMPLETION eted operations. (Clearly stack). SEE RULE 1103. For Mark Mark 13 3/8" 54.5# K55	EXISTING PICAL ACTION OF THE PICK SUB REMEDIAL WORLD COMMENCE DR CASING TEST A CEMENT JOB OTHER:	Report or Other Dataly SEQUENT REPORT, KK AND PLUG A ABANDO ABANDO	OF: ND □ ONMENT ing estimated date oposed completion
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole 03/06/04 TD 17 ½" hole @ 1950".	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly stank). SEE RULE 1103. For Man Man For Man Man For Man	EXISTING PICAL ACTION OF THE PICK SUB REMEDIAL WORLD COMMENCE DR CASING TEST A CEMENT JOB OTHER:	Report or Other Dataly SEQUENT REPORT, KK AND PLUG A ABANDO ABANDO	OF: ND □ ONMENT ing estimated date oposed completion
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole 03/06/04 TD 17 ½" hole @ 1950'. If see the see th	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly stank). SEE RULE 1103. For Man 47 jts 13 3/8" 54.5# K55 urface. WOC 22 hrs. Held.	EXISTING PICATE AND ADDRESS OF THE PICATE	Report or Other Data Page 18 SEQUENT REPORT, OCO STAND PLUG A ABANDO ND PLUG A ABANDO MD PROPERTION OF THE PAGE 18 ABANDO MD PAGE 18 ABAND	OF: NG CASING ND ONMENT ing estimated date oposed completion ass C. Tail w/300
12. Check A NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion. 03/01/04 Spud 17 ½" hole 03/06/04 TD 17 ½" hole @ 1950'. Is sx Class C. Circ 100 barrels cmt to st 03/08/04 Pressure test csg to 1000#.	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly stank). SEE RULE 1103. For Man 47 jts 13 3/8" 54.5# K55 urface. WOC 22 hrs. Held.	EXISTING PICATE AND ADDRESS OF THE PICATE	Report or Other Data Page 18 SEQUENT REPORT, OCO STAND PLUG A ABANDO ND PLUG A ABANDO MD PROPERTION OF THE PAGE 18 ABANDO MD PAGE 18 ABAND	OF: NG CASING ND ONMENT ing estimated date oposed completion ass C. Tail w/300
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole @ 1950'. sx Class C. Circ 100 barrels cmt to st 03/08/04 Pressure test csg to 1000#. 03/16/04 TD'd 12 ¼" hole @ 5750' 03/18/04 Ran 131 jts 9 5/8" P110 40 surface off DV tool.	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly stack). SEE RULE 1103. For Mark Mark 13 3/8" 54.5# K55 arrface. WOC 22 hrs. Held. Held	EXISTING PICAL ACTION OF THE PICAL ACTION OF T	Report or Other Data P. SEQUENT REPORT, RK AGERICAN PLUG A ABANDO DE OE 62 8 ILLING OPNS PLUG A ABANDO DE OE 62 8 Ind give pertinent dates, include ttach wellbore diagram of production with the production of	OF: NG CASING ND ONMENT ing estimated date oposed completion ass C. Tail w/300
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole @ 1950'. Is X Class C. Circ 100 barrels cmt to st 03/08/04 Pressure test csg to 1000#. 03/16/04 TD'd 12 ¼" hole @ 5750' 03/18/04 Ran 131 jts 9 5/8" P110 40 surface off DV tool. 03/19/04 Cmtd Stage 2 lead w/ 1400	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly stack). SEE RULE 1103. For Mark. Ran 47 jts 13 3/8" 54.5# K55 purface. WOC 22 hrs. Held. Held. ### LT&C csg @ 5749'. Cmt. O sx 50:50 Class C tail w/200	EXISTING PICAL ACTION OF THE PICAL ACTION OF T	Report or Other Data P. SEQUENT REPORT, RK AGERICAN PLUG A ABANDO DE OE 62 8 ILLING OPNS PLUG A ABANDO DE OE 62 8 Ind give pertinent dates, include ttach wellbore diagram of production with the production of	OF: NG CASING ND ONMENT ing estimated date oposed completion ass C. Tail w/300
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole @ 1950'. sx Class C. Circ 100 barrels cmt to st 03/08/04 Pressure test csg to 1000#. 03/16/04 TD'd 12 ¼" hole @ 5750' 03/18/04 Ran 131 jts 9 5/8" P110 40 surface off DV tool.	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly stack). SEE RULE 1103. For Mark. Ran 47 jts 13 3/8" 54.5# K55 purface. WOC 22 hrs. Held. Held. ### LT&C csg @ 5749'. Cmt. O sx 50:50 Class C tail w/200	EXISTING PICAL ACTION OF THE PICAL ACTION OF T	Report or Other Data P. SEQUENT REPORT, RK AGERICAN PLUG A ABANDO DE OE 62 8 ILLING OPNS PLUG A ABANDO DE OE 62 8 Ind give pertinent dates, include ttach wellbore diagram of production with the production of	OF: NG CASING ND ONMENT ing estimated date oposed completion ass C. Tail w/300
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole @ 1950'. Is X Class C. Circ 100 barrels cmt to starting and the completion of starting and the completion. 03/08/04 TD 17 ½" hole @ 1950'. Is X Class C. Circ 100 barrels cmt to starting and the completion of starting any proposed work of starting any proposed or complete to starting any proposed work of starting any proposed or complete to starting any p	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly stack). SEE RULE 1103. For Mark. Ran 47 jts 13 3/8" 54.5# K55 arface. WOC 22 hrs. Held. Held. See State of the second o	EXISTING PICAL ACTION OF THE PICK OF THE P	Report or Other Dataly SEQUENT REPORT, KK AND PLUG A ABANDO ABANDO	OF:
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole @ 1950'. Is X Class C. Circ 100 barrels cmt to sto 3/08/04 Pressure test csg to 1000#. 03/16/04 TD'd 12 ¼" hole @ 5750' 03/18/04 Ran 131 jts 9 5/8" P110 40 surface off DV tool. 03/19/04 Cmtd Stage 2 lead w/ 1400 03/20/04 Pressure test csg to 1000#.	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION cted operations. (Clearly stack). SEE RULE 1103. For Mark. Ran 47 jts 13 3/8" 54.5# K55 arface. WOC 22 hrs. Held. Held. See State of the second o	EXISTING PICAL ACTION OF THE PICK OF THE P	Report or Other Dataly SEQUENT REPORT, KK AND PLUG A ABANDO ABANDO	OF:
12. Check A NOTICE OF IN PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed wor or recompletion. 03/01/04 Spud 17 ½" hole @ 1950'. Is X Class C. Circ 100 barrels cmt to starting and the completion of starting and the completion. 03/08/04 TD 17 ½" hole @ 1950'. Is X Class C. Circ 100 barrels cmt to starting and the completion of starting any proposed work of starting any proposed or complete to starting any proposed work of starting any proposed or complete to starting any p	ppropriate Box to Indicate Fention TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION eted operations. (Clearly stank). SEE RULE 1103. For Mark. SEE RULE 1103. For M	EXISTING PICAL ACTION OF THE PICK OF THE P	Report or Other Dataly SEQUENT REPORT, KK AND PLUG A ABANDO ABANDO	OF:

, 04/22/04	Ran 33 jts 4 1/2" 13.5# P110 LT&C liner. Cmtd w/ 175 sx Class C. Top of packer @ 11,897'.
04/24/04	Drill cement. Pull up into 7" csg. Pressure up on liner to 1500#. Held. Displace mud with KCl
04/27/04	Released rig.

I hereby certify that the information above is true and compl grade tank has been/will be constructed or closed according to NMOCI	ete to the best of my knowledge and belief. I	further certify that any pit or below-
EXISTING PIT		atternative ocb-approved pian
SIGNATURE (MAC)	_TITLE Regulatory Specialist	_DATE05/12/04
Type or print name Linda Guthrie E-mail address:	Linda.Guthrie@dvn.com Telephone No. 40:	5-228-8209
(This space for State use)		·
APPPROVED BY	TITLE	DATE
Conditions of approval, if any:	OC FIELD REPRESENTATIVE II/STAFF MA	MAY 2 4 2004

