

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTN.M. Oil Cons. Division
1025 N. French Dr.
Hobbs, NM 88240FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.5. Lease Serial 2
NM0319697
6. If Indian, Allottee or Tribe Name:
7. If Unit or CA/Agreement, Name and /or No:8. Well Name and Number:
SB FEDERAL # 1
9. API Well Number:
30-025-20915
10. Field and Pool, or Exploratory Area:
LUSK STRAWN
11. County or Parrish, State
LEA COUNTY, NM1. Type Of Well
☒ Oil Well ☐ Gas Well ☐ Other INJECTION2. Name Of Operator
Ray Westall Operating3a. Address
P.O. Box 4 - Loco Hills, New Mexico 882554. Location Of Well
1980' FNL & 660' FWL SEC 5, 19S, 32E, UL-E


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice Of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Test	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other SPUD
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert To Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed Or Completed Operation (clearly state all pertinent details, including estimated start date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in multiple completion or re-completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

05/07/04 PULL 4 1/2" CSNG FROM PART @ 4580'
SET 100' CMT PLUG 50' IN & OUT OF STUB @ 4580'
SET 100' CMT PLUG 3265'-3165'
SET 100' CMT PLUG 739'-639'
10 SXS SURFACE PLUG

HEAVY MUD BETWEEN ALL PLUGS



14. I hereby certify that the forgoing is true and correct

Name (printed/typed)

WILLIE ENGLISH

Title

Production Secretary

Signature

Date

05/07/04

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

GWW

RAY WESTALL
SB FEDERAL #1

CURRENT 5/7/04

13 3/8 48# 689' CMT CIRC
- TOL 2500' TEMP JUY

8 5/8 32# J-55 3215'

4580 PARTED CASING

SEE
change

- TOL 10480 TEMP SKY (ORIG. SGD.) GARY GOURLEY

10670 CIBP 35' CMT

11304 CIBP 35' CMT
11364 - 387 STRAWN PERES

4 1/2 11.6# N80 11440

RAY WESTALL
SB FEDERAL #1

CURRENT 5/7/04

(6)

60 Ft min Surface plug

(5) Perf/SQZE 25SX @ 700F
+ TAG

13 3/8 48" 689' CMT CIRC

TOP SALT

TOL 2500' TEMP SUX

YATES TOP 3025'

8 5/8 32" JCS 3215'

8 5/8" Shoe plug min 35SX

(4) balanced over 3215' / TAG

(3) Stub plug @ 4600' (30SX)
and TAG

4580 PARTED CASING

Polymere 5247

Bore plug 6420

(2) Perf/SQUEEZE 10,700' (50SX plug)
+ TAG

Wellcamp 10,332

TOL 10480 TEMP SUX

(1) TAG PLUG

10670 CIBP 35' CMT

STRAWN 11223

11304 CIBP 35' CMT (OK)
11364 - 387 STRAWN PERES

4 1/2 11.6" N80 11440

PIN 11010

09/22/43
OK

8/26/1993