

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

March 4, 2004

WELL API NO.
30-025-32427

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2148

7. Lease Name or Unit Agreement Name
Caprock Maljamar Unit

8. Well Number
192

9. OGRID Number
022922

10. Pool name or Wildcat
Maljamar Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
The Wiser Oil Company

3. Address of Operator
P.O. Box 2568 Hobbs, New Mexico 88241

4. Well Location
Unit Letter G : 2625 feet from the North line and 1335 feet from the East line
Section 19 Township 17S Range 33E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4117' GL

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL Sect Twp Rng Pit type Steel Depth to Groundwater 190' Distance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
 feet from the line and feet from the line

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Wiser requests approval to Plug and Abandon the well by the procedure listed below.

Perforations: 3528'-3553' Surface Casing: 1275'

1. Set CIBP @ 3500'. Cap w/50' cement. Tag cement.

2. Circulate abandonment mud.

3. Set 50' cement plug 1325'-1225'.

4. Tag cement.

5. Set 100' plug @ 400'-300'.

6. Set 50' cement plug @ surface.

7. Install dry hole marker.

5-1/2" casing set @ 5525' cement circulate

*Note: Call OCD before beginning work.

→ 2410-2310-100 PLUG

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Mary Jo Turner TITLE Production Tech II DATE May 20, 2004

Type or print name Mary Jo Turner

E-mail address: mturner@wiseroil.com

Telephone No. (505) 392-9797

(This space for State use)

APPROVED BY Hay W. Wink

Conditions of approval, if any

TITLE

OCD FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

The Wiser Oil Company
Hobbs Office
OGRID 022922

N

Pit

W

PU

E

S

CMU # 192
2625' FNL & 1335' FEL
Unit G Sec.19-T17S-R33E
Lea County, New Mexico