Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resource	Form C-103 March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II OIL CONSERVATION DIVISION	30-025-27936 33021
1301 W. Grand Ave., Artesia, NM 88210 District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Sonta Eo. NM 87505	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	 Lease Name or Unit Agreement Name Gecko 27 State
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well \square Gas Well \blacksquare Other $\leq \omega D$	1
2. Name of Operator	9. OGRID Number
Hal J. Rasmussen Operating, Inc.	9809
3. Address of Operator	10. Pool name or Wildcat
550 West Texas, Suite 200, Midland, Texas 79701	Wildcat Strawn
4. Well Location	
Unit Letter <u>A</u> : <u>660</u> feet from the <u>North</u> line a	and <u>660</u> feet from the <u>East</u> line
Section 27 Township 15S Range 38	E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, G	R, etc.)
3712' GL	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be at	
Pit Location: UL Sect Twp Pit type Depth to Ground	
Distance from nearest surface water Below-grade Tank Location ULSect	1wpKng;
feet from theline andfeet from theline	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENCE	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: REMEDIAL PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION CASING TI	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTE
NOTICE OF INTENTION TO: REMEDIAL PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE COMPLETION CASING TI CEMENT J OTHER: OTHER: OTHER:	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT OB SUBSEQUENT SUBSEQUENT REPORT OF: ALTERING CASING ABANDONMENT OB SUBSEQUENT REPORT OF: ALTERING CASING
NOTICE OF INTENTION TO: REMEDIAL PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details)	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING CASING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING ALTERING CASING ALTERING
NOTICE OF INTENTION TO: REMEDIAL PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion.	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND OB Sup \$80 Ails, and give pertiment gates, including estimated date ons: Attach wellbore diagram of proposed completion
NOTICE OF INTENTION TO: REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE COMPLETION CASING TI CEMENT J OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H".	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING ALTERING CASING ALTERING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex pump truck to perform step-rate injection test. Test lines to 5000 psi. S	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING ALTERING CASING ALTERING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION COMPLETION CASING TI OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Auge that the perform step-rate injection test. Test lines to 5000 psi. S 10/23/03 - RIH with 77 stds 3-/12" EUE tbg, 127 jts 3-1/2"PH6 12.95# tbg	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING AL
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE COMPLETION CASING TI CEMENT J OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex August to perform step-rate injection test. Test lines to 5000 psi. S 10/23/03 - RIH with 77 stds 3'/12" PH6 tbg, XO,78 stds 3-1/2" EUE, XO, 132 jts 3-1/2" EUE tbg	SUBSEQUENT REPORT OF: WORK ALTERING CASING ALTERING ALTERING CASING ALTERING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION CASING TI CEMENT J OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex pump truck to perform step-rate injection test. Test lines to 5000 psi. S 10/23/03 - RIH with 46 jts 3'1/2" EUE tbg, 127 jts 3-1/2" EUE, XO, 132 jts 3-1/2" EUE tbg 10/24/03 - RIH with 6j jts 3'1/2" PH6 tbg. 10/28/03 - RIH with 6j jts 3-1/2" EUE 8 rd IPC	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND OB SUD SO Mils, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex pump truck to perform step-rate injection test. Test lines to 5000 psi. S 10/23/03 - RIH with 77 stds 3/12" EUE tbg, 127 jts 3-1/2" EUE, XO, 132 jts 3-1/2" EUE tbg 10/28/03 - RIH with 72 jts 3-1/2" PH6 tbg. 10/28/03 - RIH with 63 jts 3-1/2" EUE 8 rd IPC 11/6/03 - Perforate. See Attached.	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND OB SUD SO Mils, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION CASING TI CEMENT J OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex pump truck to perform step-rate injection test. Test lines to 5000 psi. S 10/23/03 - RIH with 46 jts 3'1/2" EUE tbg, 127 jts 3-1/2" EUE, XO, 132 jts 3-1/2" EUE tbg 10/24/03 - RIH with 6j jts 3'1/2" PH6 tbg. 10/28/03 - RIH with 6j jts 3-1/2" EUE 8 rd IPC	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT ST AND OB SUD \$80 Altering of proposed completion wills, and give pertinent gates, including estimated date ons: Attach wellbore diagram of proposed completion H H H H H H H H H H H H H H H H H H H
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. 10/23/03 - RIH with 77 stds 3-/12" EUE tbg, 127 jts 3-1/2" PH6 12.95# tbg 10/24/03 - RIH with 72 jts 3-1/2" PH6 tbg. 10/29/03 - RIH with 72 jts 3-1/2" EUE tbg 10/28/03 - RIH with 72 jts 3-1/2" PH6 tbg. 10/29/03 - RIH with 63 jts 3-1/2" EUE 8 rd IPC 11/6/03 - Perforate. See Attached. 11/9/03 - Release rig. Date of first injection 2/24/04. 30 minute graph to follow. I hereby certify that the information above is true and complete to the best of my km	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND OB SUP \$80 Mills, and give periment dates, including estimated date ons: Attach wellbore diagram of proposed completion ee Attached HULL HULL CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CONTRACTOR CO
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI OTHER: OTHER: CASING TI 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex pump truck to perform step-rate injection test. Test lines to 5000 psi. S 10/23/03 - RIH with 77 stds 3-1/2" EUE tbg, 127 jts 3-1/2" PH6 12.95# tbg 10/24/03 - RIH with 72 jts 3-1/2" PH6 tbg. 10/29/03 - RIH with 63 jts 3'-1/2" EUE s rd IPC 11/6/03 - Perforate. See Attached. 11/9/03 - Release rig. Date of first injection 2/24/04. 30 minute graph to follow. I hereby certify that the information above is true and complete to the best of my kn	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND OB SUBSEQUENT REPORT OF: ABANDONMENT ABANDONMENT ST AND OB SUBSEQUENT REPORT OF ABANDONMENT ABANDONMEN
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. 10/23/03 - RIH with 77 stds 3-/12" EUE tbg, 127 jts 3-1/2" PH6 12.95# tbg 10/24/03 - RIH with 72 jts 3-1/2" PH6 tbg. 10/29/03 - RIH with 72 jts 3-1/2" EUE tbg 10/28/03 - RIH with 72 jts 3-1/2" PH6 tbg. 10/29/03 - RIH with 63 jts 3-1/2" EUE 8 rd IPC 11/6/03 - Perforate. See Attached. 11/9/03 - Release rig. Date of first injection 2/24/04. 30 minute graph to follow. I hereby certify that the information above is true and complete to the best of my km	SUBSEQUENT REPORT OF: .WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND ABANDONMENT OB Image: State stat
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. Tot 15/2" 17" rads 3-1/2" PH6 tbg. 12.95# tbg 10/24/03 - RIH with 7 stds 3-1/2" FUE tbg. 12.7 jts 3-1/2" PH6 12.95# tbg 10/29/03. RIH with 7 stds 3-1/2" PH6 tbg. 20,78 stds 3-1/2" EUE, XO, 132 jts 3-1/2" EUE tbg 10/29/03 - RIH with 7 jts 3-1/2" PH6 tbg. 10/29/04. 30 minute graph to follow. I I hereby certify that the information above is true and complete to the best of my kn grade tank has been/will be constructed or closed according to NMOCD guidelines], a general per SIGNATURE Mult Mult Mult All All All All All All All All All A	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND OB SUBSEQUENT REPORT OF: ABANDONMENT ABANDONMENT STAND OB SUBSEQUENT REPORT OF: ABANDONMENT ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. Tot 15/2" 17" rads 3-1/2" PH6 tbg. 12.95# tbg 10/24/03 - RIH with 7 stds 3-1/2" FUE tbg. 12.7 jts 3-1/2" PH6 12.95# tbg 10/29/03. RIH with 7 stds 3-1/2" PH6 tbg. 20,78 stds 3-1/2" EUE, XO, 132 jts 3-1/2" EUE tbg 10/29/03 - RIH with 7 jts 3-1/2" PH6 tbg. 10/29/04. 30 minute graph to follow. I I hereby certify that the information above is true and complete to the best of my kn grade tank has been/will be constructed or closed according to NMOCD guidelines], a general per SIGNATURE Mult Mult Mult All All All All All All All All All A	SUBSEQUENT REPORT OF: WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND OB SUBSEQUENT REPORT OF: ABANDONMENT ABANDONMENT STAND OB SUBSEQUENT REPORT OF: ABANDONMENT ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENC PULL OR ALTER CASING MULTIPLE CASING TI COMPLETION OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent deta of starting any proposed work). SEE RULE 1103. For Multiple Completion or recompletion. 9/21/03 - Run 5-1/2" 17" Casing - 4700' - 9850' w756 sx "H". 10/15/03 - RU Petroplex Acidizng. See attached. 10/16/03 - RU Petroplex Acidizng. See attached. Tot 15/2" 17" rads 3-1/2" PH6 tbg. 12.95# tbg 10/24/03 - RIH with 7 stds 3-1/2" FUE tbg. 12.7 jts 3-1/2" PH6 12.95# tbg 10/29/03. RIH with 7 stds 3-1/2" PH6 tbg. 20,78 stds 3-1/2" EUE, XO, 132 jts 3-1/2" EUE tbg 10/29/03 - RIH with 7 jts 3-1/2" PH6 tbg. 10/29/04. 30 minute graph to follow. I I hereby certify that the information above is true and complete to the best of my kn grade tank has been/will be constructed or closed according to NMOCD guidelines], a general per SIGNATURE Mult Mult Mult All All All All All All All All All A	SUBSEQUENT REPORT OF: .WORK ALTERING CASING .CE DRILLING OPNS. PLUG AND .ABANDONMENT EST AND OB Supple SD Image: Strate of the strate