

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. <b>30-041-20066</b>
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> <input checked="" type="checkbox"/> <b>Injection</b>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <b>Chi Operating, Inc.</b>		6. State Oil & Gas Lease No. <b>25945</b>
3. Address of Operator <b>P.O. Box 1799, Midland, Texas 79702</b>		7. Lease Name or Unit Agreement Name: <b>Hondo State</b>
4. Well Location Unit Letter <b>F</b> : <b>1,980</b> feet from the <b>North</b> line and <b>1,980</b> feet from the <b>West</b> line Section <b>31</b> Township <b>7-S</b> Range <b>33-E</b> NMPM County <b>Roosevelt</b>		8. Well No. <b>#1</b>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat <b>SWD; Chavaroo San Andres</b>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

**03/31/04** Notified OCD, Gary Wink, reviewed plugging procedure. MIRU Triple N rig #23 and plugging equipment. ND wellhead, NU BOP. POOH tubing & packer. RIH w/ RBP, unable to set. SDFN.

**04/01/04** OCD Billy Prichard, on location. Attempted to RBP, unable. POOH and w/ tbg-set CIBP, set CIBP @ 4,135'. Circulated hole w/ mud, pumped 25 sx C cmt 4,135 - 3,767'. POOH w/ tbg. RIH w/ wireline and cut casing @ 1,924'. Worked casing, not free. RIH w/ packer, established rate of 2½ BPM @ 1,000 psi, no returns in 4½ x 8½", and squeezed 45 sx C cmt w/ CaCl₂ @ 1,924', ISIP 800 psi. SDFN.

**04/02/04** Notified OCD, Billy Prichard. Tagged cmt @ 1,702'. Cut csg @ 421', POOH w/ wireline. RIH w/ packer to 250' and squeezed 70 sx C cmt w/ 2% CaCl₂, displacing to 200'. WOC and tagged at 204'. Pumped 10 sx C cmt 60' to surface. RDMO.

Cut off wellhead and anchors, capped well, installed marker. Backfilled pit and cellar. Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James F. Newman TITLE engineer DATE 04/06/04

Type or print name James F. Newman, P.E. Triple N Services, Inc. Telephone No. 432-687-1994  
(This space for State use)

APPROVED BY Gary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JUN 02 2004  
Conditions of approval, if any: