<b>‰</b>			
Submit 3 Copies To Appropriate District	State of New Mo	exico	Form C-103
Office District I	Energy, Minerals and Natu	ural Resources r	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-025-33177
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION	1	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE X FEE
District IV	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			V-1222
	CES AND REPORTS ON WELLS	S	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Knowles
PROPOSALS.)  1. Type of Well:			8. Well Number
Oil Well X Gas Well	Other		1
2. Name of Operator Primal Energy Corpo			9. OGRID Number
3. Address of Operator			10. Pool name or Wildcat
	Ste. 227, Houston, T.	X 77073	Southeast Denton-Devonian
4. Well Location			
T T	3627 c. c. d. Nom	th :: 1	425 Fact from the Fact line
Unit Letter:_	1027 feet from the NOT	tine and 1	425 feet from the <u>East</u> line
Section 1	Township 16S R	ange 39E	NMPM County Lea
1	11. Elevation (Show whether DF 3717' GR		
Pit or Below-grade Tank Application (For		n C-144 must be attached	
Pit Location: ULSectTwp	RngPit type[	Depth to Groundwater	Distance from nearest fresh water well
Distance from nearest surface water	Below-grade Tank Location UL_	SectTwp	Rng;
feet from theline and	feet from theline		
12 Charle A	maraneista Day ta Indianta N	Jatura of Notice	Papart or Other Data
NOTICE OF IN	ppropriate Box to Indicate N		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK		REMEDIAL WORK	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII	
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	ABANDONMENT
. OLE ON ALIEN ON ONC	COMPLETION	CEMENT JOB	and the same of th
071150		07.155	12 13 14 75 76
OTHER:		OTHER:	
			d give pertinent dates aincluding estimated date
of starting any proposed wo or recompletion.	rk). SEE RULE 1103. For Multip	ple Completions: At	tach wellbore diagram of proposed completion
or recompletion.			REULIVED
6-01-04 Spot 30 sx cmt	. @ 11.700' WOC & +aa	a 11 300'	\\ C Hobbs
6-02-04 Circ. hole w/	salt gel mid.	G 11,500 .	OCD C
6-02-04 Spot 25 sx @ 1	0,600'.		16
6-02-04 Spot 25 sx @ 8		on page #2	08 88 88 E8 E8
			e and belief. I further certify that any pit or below-
			or an (attached) alternative OCD-approved plan .
f			
SIGNATURE	TITLE_	Agent	DATE6-07-04
Type or print name Roger Mass			
	Sev F <sub>-mail</sub> a	ddress.	Telephone No. (432) 530-0
Type of print name Roger riass	sey E-mail a	address:	Telephone No. (432) 530-0
(This space for State use)	sey E-mail a	address:	Telephone No. (432) 530-0
	sey E-mail a	address:	Telephone No. (432) 530-0
	E-mail a		Telephone No. (432) 530-0  DATE  DATE  DATE  1/5TAFF MANAGEMENT  DATE  D

Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.

## Page #2

Primal Energy Corporation Knowles #1

13. 6-02-04 Spot 25 sx @ 6,447'.
6-02-04 Spot 30 sx @ 5,120', WOC & tag @ 4,855'.
6-03-04 Spot 25 sx @ 2,196'.
6-03-04 Perforate @ 450', set pkr. @ 188', sqz. 35 sx cmt. thru perfs. WOC & tag @ 344'.
6-04-04 Spot 10 sx cmt. @ 50' to surface.
6-04-04 RDMO. Install dry hole marker & clean location.